

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
TP HSBC Xiao Tony				
Estimate of Cost of Repairs				
		Date	2-Mar-2023	
		Vehicle No.	SMS8075C	
		Model	Toyota Wish	
		CHASSIS/ENG#	JTDDGG20W40J003312	
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	RH FRONT DOOR <i>Repair</i>	1	\$1,753.70	\$1,753.70 <i>x</i>
2	RH REAR DOOR <i>Dented</i>	1	\$1,680.90	\$1,680.90 <i>1305.</i>
3	REAR DOOR BOARD <i>for</i>	1	\$861.20	\$861.20 <i>x</i>
4	REAR DOOR GEAR <i>for</i>	1	\$265.60	\$265.60 <i>x</i>
5	REAR BUMPER <i>for</i>	1	\$739.70	\$739.70 <i>586</i>
6	LH/RH BUMPER SIDE RETAINER <i>2nd RH</i>	2	\$105.50	\$211.00 <i>65.</i>
7	RIM <i>for</i>	1	\$1,978.60	\$1,978.60 <i>650(SN)</i>
			Sub-total 1	\$7,490.70
NETT ITEMS				
S/N	Item <i>for</i>	Quantity	Unit Price	Amount
1	RH FRONT DOOR STICKER <i>for</i>	1	\$40.00	\$40.00 <i>✓</i>
2	BUMPER CLIP SET <i>for</i>	1	\$50.00	\$50.00 <i>30.</i>
			Sub-total 2	\$90.00
LABOUR				
1	Remove and replace doors and components			\$300.00 <i>80.</i>
2	To knock and repair areas back to condition			\$800.00 <i>600</i>
3	To conduct wiring checks			\$80.00 <i>30.</i>
4	Spray painting on all affected parts			\$1,200.00 <i>800.</i>
			Labour Total	\$2,380.00
			Parts & Labour Total	\$9,960.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3657

h/s: 2.9K

05 Days

2.9K