



Section A - Accident Details

Registration Number	SHC4857H
Case Reference Number	TAX/02/23/2004
Registration Date	28/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LAU KHEE MENG
Type of Accident	Side Swipe
Accident Date and Time	2/Feb/2023 4:30 PM
Accident Reported Date and Time	3/Feb/2023 10:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117546
Special Instruction to ARC, if any	TP/ LEFT REAR PORTION/ AIG - LKK
Prepared Date and Time	4/Feb/2023 10:09 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$700.00
Total Spray Cost	\$2,592.00	\$950.00
Total Spare Part Cost	\$4,707.19	\$1,454.89
Total Other Cost	\$1,100.00	\$260.00
TOTAL COST	\$9,413.19	\$3,364.89
Lump Sum Total	\$9,400.00	\$3,350.00 (L/S)
Number of Repair Days	8.0	6.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / AIG
ARC / Surveyor Sign Off Date	09/02/2023 5:06 PM	09/02/2023 5:02 PM
Signature		
Remarks	<p>Surveyor agreed by the phone to changed the from initial ECD 5 days to new ECD of 6 Days.</p> <p>LUMPSUM REPAIR / AFTER REPAIR PHOTOS ,FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com</p>	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0333	Invoice Number	
Quotation Date	25.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION REAR	\$1,014.00	\$700.00 ✓
Total Labour	\$1,014.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00 ✓
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY DOOR HANDLE	\$360.00	\$0.00
Total Spray Painting & Panel Beating	\$2,592.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$240.00	\$60.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$100.00 ✓
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
Total Other Costs	\$1,100.00	\$260.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6700447210	PANEL SUB-ASSY, REAR DOOR LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace
		7586047900	MOULDING ASSY, BODY ROCKER PANEL LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	Replace
		6563847060	LINER, REAR FENDER , LH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given

R
✓ NEC
✓ BT
R
✓ BT
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2023

User ID : PohSuan

		52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		52566479 00	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given
		69210470 51A1	DOOR OUTER HANDLE FRONT_LH	0.00	\$423.20	0.00	\$0.00	Replace	Not Given
		692114- 7021A1	DOOR OUTER HANDLE REAR_LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given
Total					\$7,825.30		\$1,818.61		

R
X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,818.61
-20%
1454.89 L/S \$3,350/-
+ 700.00
+ 1210.00
3,364.89

*All X = NN