

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0122/2023/EQ
DATE : 2-Feb-23
WIP : 60861

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIU NA
ADDRESS : BLK 103 JURONG EAST STREET 13
#09-210
SINGAPORE 600103
TELEPHONE : HP +65 96738362
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210041208-01
VEHICLE NO : **SLN 4822 C**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 24/4/2021
ENGINE NO : DEM 024185
CHASSIS NO : WAUZZZF44LN013737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jan-23
PLACE OF ACCIDENT : PIE TO TUAS, AT AROUND EXIT 20A

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 4822 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓ ✓
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	600.00	X X
3	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N \$	400.00	X X
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	X ✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,400.00	X X
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	X X
TOTAL LABOUR CHARGES		:	\$	4,360.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 4822 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	750 ✓
8	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES, AND REAR END PANELLING.	\$ 6,000.00	1103 ✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 16,152.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 4822 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rehd ✓</i>	1	\$ 2,642.00 ✓	2113.60
2	REAR BUMER FIXING PARTS <i>Abc m x</i>	1	\$ 184.00 + x	
3	REAR BUMPER SECURING STRIP - UPPER <i>not ✓</i>	1	\$ 133.00 ✓	106
4	REAR BUMPER SECURING STRIP - LOWER <i>not ✓</i>	1	\$ 264.00 ✓	210.8
5	REAR BUMPER SPOILER <i>cut ✓</i>	1	\$ 292.00 ✓	233.6
6	REAR BUMPER BRACKET - LH <i>? x the new.</i>	1	\$ 241.00 ? x	
7	REAR BUMPER REFLECTOR - LH / RH <i>HH cut ✓</i>	2	\$ 102.00 ✓	51 81.12
8	REAR OUTER TAIL LIGHT - LH <i>cut ✓</i>	1	\$ 1,200.00 ✓	960
9	REAR OUTER TAIL LIGHT TRIM - LH <i>new cut ✓</i>	1	\$ 36.00 + ✓	28.08
10	REAR INNER TAIL LIGHT - LH <i>new cut ✓</i>	1	\$ 1,200.00 ✓	960
11	REAR INNER TAIL LIGHT TRIM - LH <i>new cut ✓</i>	1	\$ 36.00 + ✓	28.08
12	REAR PARKING AID SENSOR - INNER / OUTER <i>Propd.</i>	2	\$ 543.00 ? ✓	212
13	REAR PARKING AID SEAL RING <i>new x</i>	4	\$ 11.00 + x	
14	REAR BUMPER WIRING SET <i>new x</i>	1	\$ 452.00 + x	
15	REAR BOOT LID OPENING CONTROL UNIT <i>new x</i>	1	\$ 491.00 + x	
16	REAR TAILGATE OPENING SENSOR LINE <i>new x</i>	1	\$ 230.00 + x	
17	REAR AERIAL KEY ACCESS <i>2 x</i>	1	\$ 123.00 + x	
18	REAR AERIAL RETAINER - LH <i>new x</i>	1	\$ 30.00 + x	
19	REAR TELEPHONE AERIAL <i>x</i>	1	\$ 197.00 + x	
20	EXHAUST TAIL PIPE TRIM - LH <i>new cut</i>	1	\$ 406.00 x ✓	324.80
SUB TOTAL SPARE PARTS		:	\$ 8,813.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 4822 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR BUMPER GUIDE SECTION - LH <i>bu d.</i>	1	\$ 27.00	<i>✓</i> 21.36
22	REAR BUMPER HOLDING STRAP - LH / RH <i>new</i>	2	\$ 200.00	<i>✓</i> <i>✓</i>
23	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 52.00	<i>✓</i> <i>✓</i>
24	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 1,197.00	<i>✓</i> <i>✓</i>
25	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>new</i>	2	\$ 34.00	<i>✓</i> <i>✓</i>
26	PACKING ADHESIVE <i>3</i>	1	\$ 22.00	<i>✓</i> 16.88
27	AUDI EMBLEM <i>1</i>	1	\$ 152.00	<i>✓</i> 121.60
28	"A4" INSCRIPTION <i>1</i>	1	\$ 110.00	<i>✓</i> 87.60
29	REAR TAILGATE CHROME TRIM STRIP - CENTER <i>1</i>	1	\$ 288.00	<i>✓</i> 230.40
30	REAR SIDE PANEL - LH <i>new</i>	1	\$ 4,612.00	<i>✓</i> <i>✓</i>
31	REAR WINDOW	1	\$ 1,362.00	<i>✓</i> <i>✓</i>
32	REAR QUARTER WINDOW - LH	1	\$ 773.00	<i>✓</i> <i>✓</i>
33	WINDOW PRIMER	2	\$ 47.00	<i>✓</i> <i>✓</i>
34	REAR WHEEL HOUSING LINER - LH	1	\$ 281.00	<i>✓</i> <i>✓</i>
35	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	<i>✓</i> <i>✓</i>
36	ACRYLIC SEALANT <i>new</i>	S/N	\$ 180.00	<i>✓</i> <i>✓</i>
37	CAVITY WAX	S/N	\$ 140.00	<i>✓</i> <i>✓</i>
38	STONE CHIP	S/N	\$ 180.00	<i>✓</i> <i>✓</i>
39	METAL FILLER POWDER	S/N	\$ 280.00	<i>✓</i> <i>✓</i>
40	1/4 GLASS SEALANT	S/N	\$ 100.00	<i>✓</i> <i>✓</i>
41	SUNDRIES <i>new</i>	\$	500.00	<i>✓</i> 11.36
TOTAL SPARE PARTS		:	\$ 19,550.00	
TOTAL LABOUR CHARGES		:	\$ 16,152.00	
GRAND TOTAL		:	\$ 35,702.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *03/02/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT