



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0147/2023/EQ  
**DATE** : 7-Feb-23  
**WIP** : 61979

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/2/2023**  
**YOUR INSURED VEH NO : YP 7299 D**

**Lonpac Insurance BHD**

300 Beach Road  
#17-04/07, The Concourse  
Singapore 199555  
Attn: Motor Claims Dept

**OWNER'S NAME** : MR FOO SAY LOK  
**ADDRESS** : 37 CLOVER AVENUE  
SINGAPORE 579324

**TELEPHONE** : HP +65 96313130  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 5132632524  
**VEHICLE NO** : **SJD 181 X**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 16/12/2022  
**ENGINE NO** : DEM 037595  
**CHASSIS NO** : WAUZZZF55NA025026  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Feb-23  
**PLACE OF ACCIDENT** : FARLEIGH AVENUE OFFSTREET CARPARK (F0031)

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJD 181 X

| S/N                         | NATURE OF JOBS                                                                                                                                         | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.       | S/N \$ 480.00        | ✓                          |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                  | S/N \$ 400.00        | ✓ ✓                        |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 3,200.00          | 2400 ✓                     |
| 4                           | TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.                                                                                                  | \$ 3,000.00          | 2400 2,500.00              |
| 5                           | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                                  | S/N \$ 280.00        | ✓ ✓                        |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                         | S/N \$ 192.00        | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                        | <b>: \$ 7,552.00</b> |                            |

Car-in

21/2/23

wp: 61979.

Xiao Tong.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Carpac ~ Adrian.



- 5 days

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJD 181 X

### DAMAGED PARTS & PRICES

| S/N                   | PARTS DESCRIPTION                               | QTY | S/NETT      | REMARKS    |
|-----------------------|-------------------------------------------------|-----|-------------|------------|
| 1                     | FRONT BUMPER Distorted                          | 1   | \$ 2,642.00 | ✓          |
| 2                     | FRONT BUMPER SECURING STRIP XNN                 | 1   | \$ 42.00    | ?          |
| 3                     | FRONT BUMPER GRILLE - CENTER new                | 1   | \$ 231.00   | x          |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE new | 1   | \$ 310.00   | x          |
| 5                     | FRONT BUMPER AIR GUIDE - RH Deformed            | 1   | \$ 53.00    | ✓ 88/52.50 |
| 6                     | FRONT BUMPER CLOSING ELEMENT new                | 1   | \$ 310.00   | +          |
| 7                     | FRONT BUMPER AIR GUIDE GRILLE - RH cut          | 1   | \$ 159.00   | ✓          |
| 8                     | FRONT BUMPER OUTER GRILLE HOLE COVER - RH Dmg   | 1   | \$ 57.00    | ✓ 88/56.50 |
| 9                     | FRONT BUMPER TRIM - CENTER new                  | 1   | \$ 135.00   | ↓          |
| 10                    | RADIATOR GRILLE new                             | 1   | \$ 2,004.00 | x          |
| 11                    | FRONT BUMPER FOAM FILLER PIECE 3 new            | 1   | \$ 173.00   | ↓          |
| 12                    | FRONT BUMPER REINFORCEMENT BEAM 3 new           | 1   | \$ 953.00   | +          |
| 13                    | FRONT BUMPER GUIDE SECTION - RH Dmg             | 1   | \$ 43.00    | ✓ 88/42.70 |
| 14                    | FRONT BUMPER TOP COVER new                      | 1   | \$ 151.00   | +          |
| 15                    | CAUTION SIGN STICKER 3 new                      | 1   | \$ 17.00    | +          |
| 16                    | AIR CONDITIONER STICKER                         | 1   | \$ 9.00     | x          |
| 17                    | LOCK CARRIER BRACKET new                        | 1   | \$ 163.00   | x          |
| 18                    | FRONT BUMPER SUPPORT - LH / RH XNN              | 2   | \$ 68.00    | X          |
| 19                    | FRONT PARKING AID SENSOR - INNER / OUTER new    | 2   | \$ 544.00   | +          |
| 20                    | FRONT PARKING AID SENSOR - RH new               | 1   | \$ 272.00   | +          |
| SUB TOTAL SPARE PARTS |                                                 |     | \$ 8,336.00 |            |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

Remized  
Adrian Li

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5JD 181 X**

|                              |                                                      |     | DAMAGED PARTS & PRICES |                |
|------------------------------|------------------------------------------------------|-----|------------------------|----------------|
| S/N                          | PARTS DESCRIPTION                                    | QTY | S/NETT                 | REMARKS        |
| 21                           | FRONT PARKING AID SEAL RING                          | 4   | \$ 11.00               | +              |
| 22                           | FRONT BUMPER WIRING SET                              | 1   | \$ 452.00              | +              |
| 23                           | HORN LOW TONE - RH                                   | 1   | \$ 149.00              | +              |
| 24                           | HORN BRACKET - RH                                    | 1   | \$ 35.00               | +              |
| 25                           | FRONT FENDER - RH <i>Dented</i>                      | 1   | \$ 1,258.00            | —              |
| 26                           | FRONT FENDER ATTACHMENT PARTS <i>Not used</i>        | 1   | \$ 59.00               | +              |
| 27                           | FRONT FENDER CLOSING ELEMENT - RH <i>Dented</i>      | 1   | \$ 87.50               | 88.00 ✓ ? H.S. |
| 28                           | FRONT FENDER BRACKET - RH <i>Best.</i>               | 1   | \$ 43.50               | 44.00 ✓        |
| 29                           | FRONT FENDER RIVET <i>new</i>                        | 6   | \$ 24.00               | —              |
| 30                           | FRONT FENDER DEFORMATION ELEMENT - RH <i>X NN</i>    | 1   | \$ 59.00               | —              |
| 31                           | FRONT FENDER BRACKET - RH <i>Best X NN</i>           | 1   | \$ X 42.00             | ✓ ? H.S.       |
| 32                           | FRONT FENDER BRACE - RH <i>Best</i>                  | 1   | \$ 139.50              | 140.00 ✓       |
| 33                           | FRONT WHEEL HOUSING LINER - RH <i>Deformed</i>       | 1   | \$ 322.00              | —              |
| 34                           | FRONT WHEEL SPOILER - RH <i>from</i>                 | 1   | \$ 87.00               | 86.20 ✓        |
| 35                           | FRONT WHEEL SPOILER END PLATE - RH <i>NN</i>         | 1   | \$ 43.00               | X              |
| 36                           | FRONT WHEEL SPOILER STONE CHIP GUARD - RH <i>new</i> | 1   | \$ 60.00               | ✓              |
| 37                           | FRONT WHEEL SPOILER TRIM BRACKET - RH <i>X NN</i>    | 1   | \$ 29.00               | X              |
| 38                           | FRONT FENDER LEDGE COVER - LONG <i>? ? NEC</i>       | 1   | \$ 42.00               | ✓ 41.60        |
| 39                           | FRONT FENDER LEDGE COVER - RH SHORT <i>X NN</i>      | 1   | \$ 19.00               | X              |
| 40                           | HEADLIGHT COVER - RH <i>can be used</i>              | 1   | \$ 52.00               | ✓ 51.50        |
| <b>SUB TOTAL SPARE PARTS</b> |                                                      |     | <b>\$ 3,015.00</b>     |                |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJD 181 X**

|                             |                                                        |     | DAMAGED PARTS & PRICES |          |
|-----------------------------|--------------------------------------------------------|-----|------------------------|----------|
| S/N                         | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS  |
| 41                          | BONNET <i>Dented</i>                                   | 1   | \$ 3,556.00            | ✓        |
| 42                          | BONNET ATTACHMENT PARTS <i>new</i>                     | 1   | \$ 136.00              | +        |
| 43                          | BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i> | 3   | \$ 101.00              | ✓ 100.00 |
| 44                          | BONNET STRIKER - RH <i>new</i>                         | 1   | \$ 60.00               | +        |
| 45                          | BONNET LOCK <i>new</i>                                 | 1   | \$ 241.00              | +        |
| 46                          | FRONT FENDER LEDGE COVER - RH INNER <i>X NN</i>        | 1   | \$ 86.00               | X        |
| 47                          | HEADLIGHT - RH <i>cut</i>                              | 1   | \$ 8,666.00            | ✓        |
| 48                          | HEADLIGHT HOSE <i>new</i>                              | 1   | \$ 43.00               | +        |
| 49                          | LIFT CYLINDER - RH <i>new</i>                          | 1   | \$ 230.00              | +        |
| 50                          | LIFT CYLINDER BRACKET - RH <i>new</i>                  | 1   | \$ 17.00               | +        |
| 51                          | LIFT CYLINDER CORRUGATED PIPE <i>new</i>               | 1   | \$ 111.00              | +        |
| 52                          | OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>          | 1   | \$ 22.00               | ✓        |
| 53                          | RADIATOR AIR GUIDE - RH INNER <i>new</i>               | 1   | \$ 38.00               | +        |
| 54                          | RADIATOR AIR GUIDE - LH / RH OUTER <i>new</i>          | 2   | \$ 50.00               | +        |
| 55                          | FRONT FENDER CHROME TRIM - RH <i>new</i>               | 1   | \$ 181.00              | ✓ 180.50 |
| 56                          | FRONT ALUMINIUM RIM - RH <i>cut</i>                    | 1   | \$ 2,000.00            | ✓ ✓      |
| 57                          | FRONT ALUMINIUM RIM RUBBER VALVE <i>new</i>            | 1   | \$ 4.00                | +        |
| 58                          | FRONT NUMBER PLATE <i>new</i>                          | S/N | \$ 60.00               | +        |
| 59                          | SUNDRIES <i>NEC</i>                                    |     | \$ 400.00              | ✓ 16.80  |
| <b>TOTAL SPARE PARTS</b>    |                                                        | :   | \$ 27,353.00           |          |
| <b>TOTAL LABOUR CHARGES</b> |                                                        | :   | \$ 7,552.00            |          |
| <b>GRAND TOTAL</b>          |                                                        | :   | \$ 34,905.00           |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Ly  
08/02/23

16l Authorised, 05 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT