

ASS. REC. BY: Tauph

REF:

G/CT123001217/7up3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 913K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBSS494BYr Regn: 2021 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Aerox 155

c.c

155Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 3022

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3SG64202 J09/85Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110/80R14R: 140/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. 5 mmR/Bal. 5 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. _____

D.O.I. 07/02/23Survey held at Bike ProductionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

☐

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / L.B.L. (\$) _____

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 30 Jan 2023

ASSESSMENT FOR REPAIR: YAMAHA AEROX - FBS5494B

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	front mudguard	\$105.00 <i>cut</i>
1 pc	Front right fork assy	330 \$480.00 <i>bt</i>
1 pc	Front left fork assy	330 \$480.00 <i>bt</i>
1 pc	Steering stem assy	140 \$210.00 <i>bt</i>
2 pcs	Bearings	\$90.00 <i>bt</i>
1 pc	Handle bar	120 \$145.00 <i>bt</i>
1 pc	Brake lever	\$55.00 <i>cut</i>
1 pc	Right fairing assy	\$165.00 <i>cut</i>
2 pcs	Amblems @ \$25.00	\$50.00 <i>cut</i>
2 pcs	Fairing labels @ \$35.00	\$70.00 <i>cut</i>
1 pc	Headlamp assy	\$395.00 <i>cut</i>
1 pc	Left fairing assy	\$165.00 <i>cut</i>
1 pc	Center inner cover	\$155.00 <i>Run</i>
1 pc	Front right upper fairing	\$175.00 <i>cut</i>
1 pc	Right fairing smaller	\$75.00 <i>cut</i>
1 pc	Mirror	\$45.00 <i>cut</i>
1 pc	Right balancer	\$45.00 <i>cut</i>
1 pc	Floor step right	\$145.00 <i>cut</i>
1 pc	Camera	\$185.00 <i>x run</i>
1 pc	Radiator cover	\$75.00 <i>cut</i>
1 pc	Exhaust heat shield	\$105.00 <i>cut</i>
1 pc	Exhaust assy	350 \$485.00 <i>bt</i>
1 pc	Floor step lower	\$105.00 <i>cut</i>
	Less discount 10%	\$2,155.00 <i>3135</i>
		\$215.50
		\$1,939.50 <i>2821.50</i>
	<u>Special nett items</u>	
1 pc	Front sport rim	\$450.00 <i>? Run</i>
1 pc	Rear number plate	\$30.00 <i>bt</i> <i>30</i>
1)	Towing charges	\$100.00 <i>/ 80</i>
	Replace, realign and adjust above	
2)	damaged parts, check wiring and	
	lighting system	\$500.00 <i>300</i>
3)	Spray painting	\$350.00 <i>200</i>
	To remove/refit, replace (if damage) check and	
4)	straighten front forks.	\$150.00 <i>120 ?</i>
	To remove/refit, replace (if damage) check and	
5)	balance front sport rims,	\$90.00 <i>30 Run</i>
6)	Body alignment	\$350.00 <i>x run</i>
	Total Estimate	<u>\$3,959.50</u> <i>700</i>

Tan Jhi 92415749
wp 2/2/23 2200
45 Resing after repair
Tan Jhi C/Photo on
03 days

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 14 Feb 2023

SUPPLEMENTARY FOR REPAIR: YAMAHA AEROX - FBS5494B


Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Radiator	\$205.00 x m
1 pc	Front lower cover	\$125.00 de
1 pc	Front brake disk	\$115.00 x m
1 pc	Front wheel axle	\$85.00 64, 40
	Less discount 10%	\$530.00 165
		\$53.00
		\$477.00 148.50
	<u>Special nett items</u>	
1 pc	Radiator coolanr	\$55.00 x m
1)	Supplementary labour	\$150.00 x m
	Total Estimate	
		\$682.00

Note: The above estimate is subjected to the prevailing GST of 7%

Tan Li
14/2/23


For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2821.50
300
700
148.50

3700
41502950
03 days
*