

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 09 Mar 2023

Preliminary Advice

Vehicle No	: SLQ3336E	Accident Date	: 01/02/2023
Make	: MAZDA CX-30	Policy No.	: SP2001501665-01
Assignment Date	: 06/02/2023	Excess	: S\$600.00
Date of Inspection	: 07/02/2023	Est. Duration of Repair	: 4
Inspection At	: EUROKARS SERVICES PTE LTD (UBI) (HQ) 5 UBI CLOSE SINGAPORE 408605		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,622.72 (Estimate \$8,319.10 + Supplementary \$303.62)
Revised Amount	:S\$	6,851.55 (Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,851.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	57,783.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,217.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.