

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT, 23001222/49p3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDE737J

at Workshop m/s 2nd Ave

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$12k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA #2936

Veh No: SDE737J

Yr Regn: 10/07/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda Fit

c.c.

1339

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 174504

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GE6 1083251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/01/23

D.O.I. 6/12/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

By

coe unel 31-03-2024 30/145.2mtr.

NOT 89064

7/3/23 4/5 @ 8000 in hand AH long CRD \$11211.40, 58%

Date/Time, File Pass to?

☐

: Preli. Report

1) 16/3 14/14/24

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 8000)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Not Approved 4/588000
 NKK
 6/2/23
 Page No. 1
 10 days.

VEHICLE NO. SDE 737J

HONDA FIT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front bumper DIS		581.20 980.00	/
2	Front bumper side retainers DIS		3042=60 112.00	/
1	Front bumper tow cover AA		72.00	X
1	Front bumper lower grille TWI		94.20 172.00	/
1	Front bumper lower cover A7		128.00	X
1	Front bumper reinforcement DIS		242.60 582.00	/
1	Bonnet BUL		680.20 1145.00	/
1	Bonnet inner lock BUL		145.00 198.00	/
1	Bonnet lock catch NS		48.00	X
2	Bonnet hinges @72.00 BUL		144.00	/
1	Bonnet insulator NF		198.00	X
1	Bonnet stand A7		52.00	X
2	Bonnet rubber stopper A7		24.00	X
1	Bonnet rubber beading A7		92.00	X
1	LHS Front fender BUL		455.20 798.00	/
1	LHS Front fender inner splash shield TIN		121.00	/
1	RHS Front fender R		798.00	X
1	RHS Front fender inner splash shield A7		121.00	X
2	RHS & LHS Fender signal lamp A7	REFIX	0.00	X
2	RHS & LHS Headlamp @892.00 CMA	680x2=1360	1784.00	/
2	RHS & LHS Headlamp lower bracket @112.00 CMA	58x2=116	224.00	/
1	Front centre radiator grille DIS		182.00 328.00	/
1	Front centre radiator grille badge MS		45 72.00	/
1	Front support panel BUL		472.60 580.00	/
1	Radiator BUL/PAN		650.00	/
1	Radiator spare tank DE		86.50 120.00	/
1	Radiator fan motor JM		180.00	/
1	Air con condensor BUL		750.00	/
1	Air con condensor pipe BUL		110.00	/
1	Air con condensor pipe to valve A7		180.00	X
1	Front engine intake manifold	TO CHECK A7	0.00	X
1	Front engine	TO CHECK A7	0.00	X
2	Front engine mounting	TO CHECK A7	0.00	X
2	RHS & LHS Front chassis extension \$672	R	1344.00	X
2	Horns \$75 CM		150.00	/
1	LHS side view mirror A7		568.00	X
1	Front windscreen A7		980.00	X
1	Front windscreen moulding A7		158.00	X
1	Front wiper washer tank DE	105.30	172.00	/
1	Front wiper garnish A7		200.00	X
	PARTS C/F		14335.00	

VEHICLE NO. SDE 737J

HONDA FIT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	14335.00	
2	RHS & LHS Front shock absorber \$328		17 656.00	X
1	LHS Front lower arm		17 298.00	X
1	LHS Front knuckle arm		17 272.00	X
1	LHS Front tie rod		17 112.00	X
1	Front driver (steering) airbag		Actual 980.00	✓
1	Front passenger airbag		Actual 1100.00	✓
1	Airbag sensor	495	Actual 580.00	✓
			18333.00	
		less 20%	3666.60	20%
			14666.40	
	<u>SPECIAL NETT ITEMS</u>			
1set	Front bumper clips		net 60.00	30
1	Front licence plate w/holder		net 75.00	40
1	Radiator coolant		net 60.00	30
1set	Front fender shield clips		net 120.00	30
2	RHS & LHS Front sports rim \$780		17 1560.00	X
1	Front dashboard		17 950.00	X
1	Front windscreen sealant		17 80.00	X
2	RHS & LHS Sports rim \$780		17 1560.00	X
1set	Bonnet insulator clips		17 80.00	X
	TOTAL PARTS		19211.40	

VEHICLE NO. SDE 737J HONDA FIT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1600.00 —	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00 —	980
3	To remove, refix wiring system at accident damaged areas and focus headlamp beam	180.00	30
4	To remove and replace radiator, pressure test and refill coolant	120.00 }	100
5	To remove and replace air con condensor, vacuum and refill gas	150.00 }	
6	To remove and replace front undercarriage parts	200.00 —	111X
7	To remove and replace front windscreen	120.00 —	111X
8	To carry out front computerised wheel alignment test	100.00 —	111X
9	To remove and replace airbags and sensors	200.00 —	✓
10	To provide anti-rust treatment on affected areas	180.00	100
	Labour Total :	3850.00	
	TOTAL (PARTS & LABOUR):	23061.00	

PRELIMINARY ESTIMATE

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-9305-60
212
7444.64
130