

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	14/01/2023
Vehicle Reg. No.:	SMQ7950T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL ASTRA, 1.6 H (A)	Vehicle Reg. Date:	02/12/2019
Vehicle Colour:	GREEN		
Engine No:	A2183339JR5X0002	Chassis No:	WOVBD8EG5K8031238
Odometer:	160110 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	18		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

Not Authored
Ex 20000

COST OF CLAIMS

	Amount
Parts	80,905.00
Miscellaneous Items	261.00
Labour	6,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	87,816.00
+ GST 8.00% (\$\$)	7,025.28
Nett Amount (\$\$)	94,841.28

This claim is handled by: **LEONG CHEE KWONG**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Feb 2023)

Parts: 144 **OPEL ASTRA 1.6 H (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: Munich Autocare Pte Ltd/SMQ7950T/03/02/2023 17:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1	39200054	*FRONT W/SCREEN	CM	0.00	0.00	*913.00 F	✓
2	1	39041883	*WINDSCREEN MOULDING LH	M	0.00	0.00	*54.00 F	✓
3	1	39041884	*WINDSCREEN MOULDING RH	M	0.00	0.00	*54.00 F	✓
4	1	39085190	*FRONT DASH BOARD	T	0.00	0.00	*2,500.00 F	✓
5	1	39117471	*FRONT DOOR PILAR LH	R	0.00	0.00	*1,007.00 F	X
6	1	39054067	*FRONT BONNET	R	0.00	0.00	*1,077.00 F	✓
7	1	39034618	*FRONT BONNET INSULATOR		0.00	0.00	*295.00 F	?
8	1	39032149	*BONNET HINGLE LH	DIT	0.00	0.00	*34.00 F	✓
9	1	39032150	*BONNET HINGLE RH	DIT	0.00	0.00	*34.00 F	✓
10	1	39150203	*FRONT ENGINE HARNESS WIRE		0.00	0.00	*340.00 F	?
11	1	39052728	*FRONT BUMPER	T	0.00	0.00	*1,322.00 F	✓
12	1	13423599	*FRT BUMPER TOW COVER	M	0.00	0.00	*51.00 F	✓
13	1	39089203	*FRT BUMPER LOW LIP RH	DIT	0.00	0.00	*171.00 F	✓
14	1	39058200	*FRT BUMPER SIDE RETAINER LH - GUIDE	CM	0.00	0.00	*53.00 F	✓
15	1	39086895	*FRT BUMPER SIDE RETAINER LH - UPP	CM	0.00	0.00	*25.00 F	✓
16	1	13488987	*FRT BUMPER HEADLAMP BRACKET LH	R	0.00	0.00	*244.00 F	✓
17	1	39086928	*FRT BUMPER UNDER DUST COVER	T	0.00	0.00	*104.00 F	✓
18	1	39024196	*FRT BUMPER BRACKET TOP CENTRE	CM	0.00	0.00	*142.00 F	✓
19	1	39015887	*FRT BUMPER SPONGE	CM	0.00	0.00	*198.00 F	✓
20	1	39151027	*FRT BUMPER REINFORCEMENT LOW (firbe)	CM	0.00	0.00	*238.00 F	✓
21	1	39160863	*FRT BUMPER REINFORCEMENT UPP (metal)	R	0.00	0.00	*599.00 F	✓
22	1	39150203	*FRT BUMPER PARKING SENSOR WIRE HARNESS	T	0.00	0.00	*340.00 F	✓
23	1	39089229	*FRT GRILLE FRAME	CM	0.00	0.00	*421.00 F	✓
24	1	39132771	*FRT GRILLE BASE	CM	0.00	0.00	*131.00 F	✓
25	1	13423642	*FRT GRILLE CHROME MOLDING RH	M	0.00	0.00	*208.00 F	✓
26	1	13423641	*FRT GRILLE CHROME MOLDING LH	M	0.00	0.00	*208.00 F	✓
27	1	39086922	*FRT GRILLE LOGO	M	0.00	0.00	*115.00 F	✓
28	1	39089220	*FRT LOW CENTRE GRILLE	DIT	0.00	0.00	*145.00 F	✓
29	1	13469598	*FRT LOW GRILLE LH	M	0.00	0.00	*74.00 F	✓
30	1	13469599	*FRT LOW GRILLE RH	M	0.00	0.00	*74.00 F	✓
31	1	39081895	*HEADLAMP RH	CM	0.00	0.00	*641.00 F	✓
32	1	39081894	*HEADLAMP LH	R	0.00	0.00	*641.00 F	✓
33	1	39078245	*HEADLAMP BALLAST LH	M	0.00	0.00	*518.00 F	✓
34	1	39150203	*FRONT HARNESS WIRE FOG LAMP	T	0.00	0.00	*340.00 F	✓
35	1	39098907	*FRONT FOG LAMP LH	M	0.00	0.00	*284.00 F	✓
36	1	13481997	*FRONT FOG LAMP COVER LH	M	0.00	0.00	*174.00 F	✓
37	1	39011390	*FRT FENDER LH	R	0.00	0.00	*465.00 F	✓
38	1	13412038	*FRT FENDER BRACKET LH	R	0.00	0.00	*69.00 F	✓
39	1	39115548	*FRT FENDER INNERSHIELD LH	T	0.00	0.00	*101.00 F	✓
40	1	39161712	*FRT WHEELHOUSE PANEL LH	R	0.00	0.00	*589.00 F	✓
41	1	39179270	*RADIATOR SUPORT PANEL TOP GARNISH RH		0.00	0.00	*22.00 F	?

Munich Autocare Pte Ltd/SMQ7950T/03/02/2023 17:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
42	1	39179271	*RADIATOR SUPORT PANEL TOP GARNISH LH	mi	0.00	0.00	*22.00 F	✓
43	1	39179263	*RADIATOR SUPORT PANEL TOP	B	0.00	0.00	*33.00 F	✓
44	1	39072522	*FRT HEADLAMP PANEL RH		0.00	0.00	*58.00 F	?
45	1	39185893	*RADIATOR	Rt/Rn	0.00	0.00	*891.00 F	✓
46	1	93160377	*RADIATOR COOLANT	Rn	0.00	0.00	*63.00 F	✓
47	1	39013322	*RADIATOR FAN BLADE & MOTOR WITH COWLING	CM	0.00	0.00	*1,269.00 F	✓
48	1	39041025	*RADIATOR TOP BRACKET LH	mi	0.00	0.00	*45.00 F	✓
49	1	39041026	*RADIATOR TOP BRACKET RH		0.00	0.00	*45.00 F	?
50	1	13306606	*RADIATOR TOP MOUTING		0.00	0.00	*8.00 F	?
51	1	13466590	*RADIATOR BRACKET LOWER LH		0.00	0.00	*43.00 F	?
52	1	39162457	*RADIATOR BRACKET LOWER RH		0.00	0.00	*43.00 F	?
53	1	39011385	*A/C CONDENSER	B	0.00	0.00	*858.00 F	✓
54	1	13356636	*A/C CONDENSER TOP SEAL	Rn	0.00	0.00	*6.00 F	✓
55	1	13487731	*A/C CONDENSOR AIR GUIDE TOP CENTRE	CM	0.00	0.00	*33.00 F	✓
56	1	39179268	*A/C CONDENSER AIR GUIDE LH	CM	0.00	0.00	*33.00 F	✓
57	1	39025943	*A/C PIPE (comp to cooling coil)	B	0.00	0.00	*678.00 F	✓
58	1	39121589	*A/C PIPE (cooling coil to condenser)		0.00	0.00	*666.00 F	?
59	1	55510769	*INTERCOOLER, TURBO CHARGER	Rt/Rn	0.00	0.00	*3,434.00 F	✓
60	1	39014321	*INTERCOOLER HOSE(turbo to intercooler), INLET		0.00	0.00	*161.00 F	?
61	1	39017740	*INTERCOOLER HOSE(intercooler to throttle body), OUTLET		0.00	0.00	*92.00 F	?
62	1	39185909	*A.T.F COOLER		0.00	0.00	*642.00 F	?
63	1	13479898	*HORN	mi	0.00	0.00	*83.00 F	✓
64	1	39155356	*WASHING TANK		0.00	0.00	*96.00 F	?
65	1	39019198	*FRONT FUSE BOX TOP COVER	CM	0.00	0.00	*39.00 F	✓
66	1	13504470	*FRONT AIR BAG IMPACT SENSOR	Rn	0.00	0.00	*295.00 F	✓
67	1	39030033	*FRONT PASSENGER DASH BOARD AIG BAG	Buss	0.00	0.00	*2,291.00 F	✓
68	1	13434703	*FRONT DRIVER STEERING AIR BAG	✓	0.00	0.00	*2,291.00 F	✓
69	1	39136242	*FRONT DRIVER STEERING WHEEL CLOCK SPRING	Rn	0.00	0.00	*87.00 F	✓
70	1	13520997	*AIR BAG CONTROL UNIT	Rn	0.00	0.00	*87.00 F	✓
71	1	39201593	*FRONT DRIVER SEAT BELT RH	Tn	0.00	0.00	*655.00 F	✓
72	1	39016993	*FRT DRIVER SEAT BELT BUCKLE RH		0.00	0.00	*655.00 F	?
73	1	39141277	*FRT DRIVER SEAT BELT PRETENSIONER RH		0.00	0.00	*208.00 F	?
74	1	39201592	*FRT PASSENGER SEAT BELT LH	Tn	0.00	0.00	*621.00 F	✓
75	1	39016995	*FRT PASSENGER SEAT BELT BUCKLE LH		0.00	0.00	*125.00 F	?
76	1	39141278	*FRT PASSENGER SEAT BELT PRETENSIONER LH		0.00	0.00	*208.00 F	?
77	1	39201587	*RR PASSENGER SEAT BELT RH		0.00	0.00	*633.00 F	?
78	1	39201587	*RR PASSENGER SEAT BELT LH		0.00	0.00	*633.00 F	?
79	1	13409378	*RR PASSENGER SEAT BELT BUCKLE RH		0.00	0.00	*209.00 F	?
80	1	13409377	*RR PASSENGER SEAT BELT BUCKLE LH		0.00	0.00	*209.00 F	?
81	1	39052731	*Trim Assy, Rear Quarter, Upper, LH		0.00	0.00	*83.00 F	?
82	1	39052732	*Trim Assy, Rear Quarter, Upper, RH		0.00	0.00	*83.00 F	?
83	1	39040243	*Trim, Rear Pillar, Lower, LH		0.00	0.00	*56.00 F	?
84	1	39040242	*Trim, Rear Pillar, Lower, RH		0.00	0.00	*56.00 F	?
85	1	39052086	*FRON TOP SUPPORT PANEL	B	0.00	0.00	*205.00 F	✓
86	1	13479548	*HARNESS ASSY HEADL		0.00	0.00	*2,947.00 F	?
87	1	39185909	*INTERCOOLER TURBO ASSY		0.00	0.00	*514.00 F	?
88	1	39115547	*FRONT FENDER LINER LH	mi	0.00	0.00	*80.00 F	✓
89	1	39142248	*SHIELD , ENGINE INSULATOR		0.00	0.00	*486.00 F	?
90	1	95523513	*GEARBOX ASSY	ltoss CM	0.00	0.00	*12,191.00 F	✓
91	1	93169007	*HEADLAMP BULB H7	Rn	0.00	0.00	*16.00 F	✓
92	1	93169009	*HIGH BEAM BULB H1	Rn	0.00	0.00	*15.00 F	✓
93	1	556601366	*ECM MODULE		0.00	0.00	*1,951.00 F	?
94	1	39158969	*BOX ASSY, ENGINE COMP WITH FUSE AND RELAY		0.00	0.00	*1,362.00 F	?
95	1	39045963	*HOUSING ASSY FUSE BOX ENGINE COMP		0.00	0.00	*77.00 F	?
96	1	13446496	*BOX FUSE INST PANEL		0.00	0.00	*292.00 F	?

Munich Autocare Pte Ltd/SMQ7950T/03/02/2023 17:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
97	1	13479548	*HARNESS ASSY HEADLAMP	0.00	0.00	*1,017.00 F	?
98	1	39150203	*HARNESS ASSY FRONT BUMPER	0.00	0.00	*340.00 F	?
99	1	39176683	*HARNESS ASSY ENGINE CONT MODULE	0.00	0.00	*1,975.00 F	?
100	1	13406411	*CABLE , ALTERNATOR & STARTER	0.00	0.00	*351.00 F	?
101	1	13447589	*PARKING ASSIST FRONT ALL SENSOR	0.00	0.00	*200.00 F	?
102	1	39158969	*BOX ASSY, ENGINE COMP WITH FUSE AND RELAY	0.00	0.00	*675.00 F	?
103	1	13446496	*BOX FUSE INST PANEL	0.00	0.00	*159.00 F	?
104	1	39150203	*HARNESS ASSY FRONT BUMPER	0.00	0.00	*1,370.00 F	?
105	2	13447589	*PARKING ASSIST FRONT ALL SENSOR	0.00	0.00	*400.00 F	?
106	1	39132816	*AIRBAG, FRONT PASSENGER DASHBOARD	0.00	0.00	*2,086.00 F	?
107	1	39177112	*AIRBAG, STEERING, DRIVER	0.00	0.00	*2,965.00 F	?
108	1	39024544	*FRONT TYRE RIM 16	0.00	0.00	*289.00 F	?
109	1	YQ00956280	*PRESSURE TYRE SENSOR	0.00	0.00	*164.00 F	?
110	1		*FRONT GROSSMEMBER ASSY	0.00	0.00	*1,680.00 F	?
111	1	95522359	*Frt Driveshaft LH	0.00	0.00	*1,300.00 F	?
112	1	95529431	*Frt Steering Rack Assy	0.00	0.00	*1,972.00 F	?
113	1	39039573	*Frt Shock Absorber LH	0.00	0.00	*330.00 F	?
114	1	39089344	*Frt Shock Absorber RH	0.00	0.00	*652.00 F	?
115	1	39030299	*Frt Knuckle Arm LH	0.00	0.00	*547.00 F	?
116	1	13517459	*Frt Wheel Hub LH	0.00	0.00	*609.00 F	?
117	1	42705813	*Frt Stabilizing Bar Link Rod LH	0.00	0.00	*102.00 F	?
118	1		*REAR CONSOLE BOX	0.00	0.00	*390.00 F	?

F=Franchise part.

Sub Total (S\$)	73,550.00
+ Margin on L,N Items 10.00% (S\$)	7,355.00
Total Parts (S\$)	80,905.00

Munich Autocare Pte Ltd/SMQ7950T/03/02/2023 17:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	7	FENDER INNER SHIELD CLIP LH	49.00
2	6	FRONT RADIATOR TOP GARNISH CLIPS LH/RH	42.00
3	1	FRONT W/SCREEN SEALANT	35.00
4	1	FRONT WHEEL TYRE	110.00
5	1	TRANSMISSION OIL	25.00
Sub Total (S\$)			261.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REFIX FRONT WINDSCREEN	New	120.00
2	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET, BUMPER, SUPPORT PANEL, FENDER LH, WHEEL HOUSE LH CHASSIS LH/RH AND DAMAGE AREA	New	1,800.00
3	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00
4	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
5	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	350.00
6	TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00
7	TO REFILL A/COND GAS	New	120.00
8	TO REPLACE FRONT SEATS BELTS, BUCKLE & PRETENSIONER LH/RH AND REAR SEATS BELT, BUCKLE & PRETENSIONER LH/RH	New	350.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00
10	TO REMOVE AND REPLACE FRONT WINDSCREEN GLASS FITTINGS AND PERFORM WATER SEEPAGE	New	120.00
11	TO REMOVE AND REPLACE AUTO TRANSMISSION	New	350.00
12	TO REMOVE AND INSTALL ENGINE AND MOUNTING AND REPAIR JOB IN FRONT WHEEL HOUSING PANEL	New	600.00
13	TO REMOVE AND INSTALL FRONT SUSPENSION, FRONT CROSSMEMBER AND CONTROL UNDERCARRIAGE SYSTEM	New	600.00
14	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER, FRONT BUMPER, SUPPORT PANEL, FRONT FENDER LH WHEEL HOUSE AND POLISH DAMAGE AREAS	New	1,500.00
15	RECOMMENDED TOTAL LOSS	New	0.00
Gross Labour Cost (S\$)			6,650.00

Munich Autocare Pte Ltd/SMQ7950T/03/02/2023 17:11 Not valid without Reference section.

Generated using Merimen Claims LEAS

< END OF ESTIMATES >

Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: