

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 3146A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED/ CRACKED	482.00	482.00
2	REAR BUMPER RETAINER	SERVICEABLE	145.40	-
1	REAR BUMPER ENFORCEMENT	SERVICEABLE	117.50	-
2	REAR BUMPER REFLECTOR	SERVICEABLE	74.40	-
1	LID	BENT	754.30	754.30
1	LID LOCK	DENTED	96.50	96.50
2	LID REFLECTOR	SERVICEABLE	116.60	-
1	LID CHROME HANDLE	SERVICEABLE	332.98	-
1	LID - 1.6 EMBLEM	NECESSARY	32.10	32.10
1	LID - VVTI EMBLEM	NECESSARY	38.40	38.40
1	LID - COROLLA EMBLEM	NECESSARY	45.00	45.00
1	LID - ELEGANCE EMBLEM	NECESSARY	44.10	44.10
1	BOOT WEATHERSTRIP	SERVICEABLE	175.35	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	702.90	-
1	END PANEL	TO REPAIR SEE LABOUR	581.20	-
1	END PANEL TOP GARNISH	SERVICEABLE	185.20	-
2	TAILAMP	O/S CRACKED/ N/S SERVICEABLE	563.80	281.90
	LESS 25% DISCOUNT		-1,121.93	-443.57
			3,365.80	1,330.73
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	CRACKED	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	REMOVE DAMAGED PARTS & ATTACHMENTS CUT/WELD DAMAGED PANEL REPAIR DENTED AREA REPLACE/REALIGN ALL PARTS INTO SAME POSITION. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND END PANEL.		1,100.00	500.00

Report Ref No. CS/LIP23001230/Kqy3m4



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY PAINT.		1,000.00	600.00
			2,100.00	1,100.00
	GRAND TOTAL		5,685.80	2,630.73

RECOMMENDED COST OF LUMP SUM REPAIRS	2,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP23001230/Kqy3m4

MARKET VALUE: \$21,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,048.00=NETT VALUE: \$6,952.00

KONG SENG CHEONG

**Licensed Appraiser**