

Vehicle Damage Assessment Report for [SMF8019J]

Estimate Created: 24/04/2023 15:34 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 24/04/2023 15:45 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mazda	Model	3
Engine Type			
License Plate Number	SMF8019J	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$3,400.00 WITH 4 WORKING DAYS	Insurlogic 4 (24/04/2023 15:45)
--	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear bumper		1	1028.60	-20.00 %	822.88
Rear bumper side holder - LH & RH		2	36.10	-20.00 %	57.76
Rear bumper tow cover		1	38.10	-20.00 %	30.48
Rear bumper reinforcement		1	498.40	-20.00 %	398.72
Rear end panel		1	0.00	-20.00 %	0.00
Rear end panel top garnish		1	214.20	-20.00 %	171.36
Bootlid		1	1066.20	-20.00 %	852.96
Bootlid lock		1	225.20	-20.00 %	180.16
Mazda logo		1	56.90	-20.00 %	45.52
Mazda 3 wording		1	59.40	-20.00 %	47.52
Skyactiv emblem		1	63.60	-20.00 %	50.88

Parts Subtotal 2,658.24

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear bumper clips		1.0	30.00	0.00 %	30.00
Reverse sensor		1.0	200.00	0.00 %	200.00
Rear end panel top garnish clips		1.0	20.00	0.00 %	20.00

Materials Subtotal 250.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	500.00	0.00 %	500.00
To check wiring system	RnR	30.00	0.00 %	30.00
To apply anti rust proofing.	RnR	40.00	0.00 %	40.00
To remove upholstery	RnR	30.00	0.00 %	30.00
To transfer bootlid fittings	RnR	80.00	0.00 %	80.00
To remove reverse sensor	RnR	50.00	0.00 %	50.00

Paint

Spray painting	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		730.00
		Paint Labor Subtotal		600.00
		Labor Subtotal		1,330.00

Summary

Repair Cost	4,238.24
Discount(20 %)	(847.65)
	3,390.59
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,390.59