

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985
 Tel : 6829 - 9170
 Fax : 6829 - 9247

Version

Quotation

DATE : 18.01.2023
 VEH NO : SMF8019J
 MODEL : Mazda 3
 D O A : 11.01.2023
 YR REF : GBJ1656A

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMF8019J (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO LIST ITEMS</u>			
1	Rear Bumper <i>Deformed</i>	1	1,028.60 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	72.20 ✓
3	Rear Bumper Side Reflector - LH & RH <i>new</i>	2	115.00 x
4	Rear Bumper Tow Cover <i>Deformed</i>	1	38.10 ✓
5	Rear Bumper Reinforcement <i>Dented</i>	1	498.40 ✓
6	Rear End Panel <i>Repair</i>	1	586.20 x
7	Rear End Panel Top Garnish <i>Deformed</i>	1	214.20 ✓
8	Taillamp - LH & RH <i>new</i>	2	1,734.40 x
9	Bootlid <i>Dented</i>	1	1,066.20 ✓
10	Bootlid Lock <i>2nd</i>	1	225.20 ✓
11	Bootlid Weatherstripe <i>new</i>	1	135.60 x
12	Bootlid Reflector - LH & RH <i>new</i>	2	590.00 x
13	Mazda Logo <i>2</i>	1	56.90 ✓
14	Mazda 3 Wording <i>new</i>	1	59.40 ✓
15	SkyActiv Emblem <i>new</i>	1	63.60 ✓
16	Spare Tyre Panel Top Cover <i>new</i>	1	368.20 x
			\$ 6,852.20
Less 20%			(1,370.44)
			\$ 5,481.76

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
2	Reverse Sensor <i>Damaged</i>	1 set	280.00 <i>250</i> ✓
3	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00 ✓
4	Rear End Panel Sealant <i>new</i>	1	60.00 x

Total Parts \$ 5,871.76

RE : ESTIMATE FOR ACCIDENT REPAIR SMF8019J (MAZDA 3)

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	500
2	To putty & spray up paint works	\$	1,200.00	600
3	To check wiring system	\$	100.00	30
4	To spray tuff coat	\$	150.00	40
5	To remove upholstery	\$	150.00	30
6	To transfer bootlid fittings	\$	150.00	80
7	To remove reverse sensor	\$	100.00	50
Total Labour		\$	3,050.00	
Grand Total		\$	8,921.76	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4238.24
2/s : 3.4K.
04 Days.