

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23001233/RQY3Q2**Date:** 03/07/2023**REFERENCE**

Insured/Claimant:	WONG SIEW JOO	Policy No:	DMPG22009893	
Date of Loss:	23/01/2023	Nature of Claim:	OD	Claim No: CDMPG23000185

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1166K		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED & NAV) (A)	Engine No:	CHZC27818
Reg. Date:	26/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V7K1025599
Colour:	Red	Odometer:	43451 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,823.00	17,442.90	14,380.10	45.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,902.00	11,012.00	3,890.00	26.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,725.00	28,454.90	18,270.10	39.10
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	45,725.00	27,454.90	18,270.10	39.96
+ GST 8.00/8.00% (S\$)	3,658.00	2,196.39	1,461.61	39.96
Nett Amount (S\$)	49,383.00	29,651.29	19,731.71	39.96

INSPECTION

Date of Assignment:	03/02/2023	
Date Inspected:	08/02/2023	Inspected At: 24 BENOI SECTOR
Estimated Period of Repair:	8.0 days	Repairer: Premium Automobiles Pte Ltd (UBI)

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2023)
Parts:	144	AUDI A3 999cc SEDAN 1.0 TFSI S TRONIC (LED & NAV) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP1166K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER CLOSING ELEMENT -RH	Missing	337.00 FS	*336.50 FS
2	1		*FRONT BUMPER GUIDE SECTION -RH	Cracked	46.00 FS	*45.40 FS
3	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	224.00 FS	*- FS
4	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	974.00 FS	*974.00 FS
5	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	144.00 FS	*- FS
6	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
7	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
8	1		*HORN LOW TONE -RH	Cracked	225.00 FS	*224.50 FS
9	1		*FRONT FENDER -RH	Buckled	1,012.00 FS	*1,012.00 FS
10	5		*FRONT FENDER RIVET	Necessary	20.00 FS	*20.00 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	80.00 FS	*- FS
12	1		*FRONT FENDER BRACKET -RH CENTER	Bent	57.00 FS	*56.10 FS
13	1		*FRONT FENDER BRACE	Bent	114.00 FS	*114.00 FS
14	1		*FRONT FENDER BRACKET -RH REAR	Deformed	38.00 FS	*37.50 FS
15	1		*FRONT FENDER INSULATION -RH	Not Necessary	51.00 FS	*- FS
16	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	39.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER -RH	Deformed	198.00 FS	*197.50 FS
18	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	99.00 FS	*- FS
19	1		*BONNET	Buckled	3,412.00 FS	*3,412.00 FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	182.00 FS	*- FS
21	2		*BONNET HINGE -LH/RH	Not Necessary	146.00 FS	*- FS
22	1		*BONNET EDGE PROTECTION	Necessary	33.00 FS	*32.80 FS
23	1		*BONNET STRIKER -RH	Not Necessary	130.00 FS	*- FS
24	1		*BONNET LOCK	Not Necessary	241.00 FS	*- FS
25	1		*BONNET CATCH HOOK	Not Necessary	106.00 FS	*- FS
26	1		*BONNET CATCH HOOK	Not Necessary	75.00 FS	*- FS
27	1		*BONNET BOWDEN CABLE -CENTER	Not Necessary	67.00 FS	*- FS
28	1		*BONNET RELEASE CABLE COVER	Not Necessary	12.00 FS	*- FS
29	1		*BONNET LOCK CABLE	Not Necessary	87.00 FS	*- FS
30	1		*BONNET ENGINE SOUND ABSORBER	Not Necessary	260.00 FS	*- FS
31	1		*FRONT PLENUM CHAMBER COVER	Not Necessary	211.00 FS	*- FS
32	1		*BONNET SIDE SEAL -RH	Not Necessary	51.00 FS	*- FS
33	1		*HEADLIGHT -RH	Broken	6,232.00 FS	*6,232.00 FS
34	1		*HEADLIGHT POWER MODULE -RH	Shorted	876.00 FS	*875.50 FS
35	1		*HEADLIGHT HEAT SINK-RH	Shorted	868.00 FS	*868.00 FS
36	1		*HEADLIGHT CONTROL UNIT	Shorted	643.00 FS	*643.00 FS
37	1		*HEADLIGHT HOSE -RH	Cut	48.00 FS	*47.90 FS
38	1		*LIFT CYLINDER -RH	Cracked	165.00 FS	*164.50 FS
39	1		*LIFT CYLINDER HOSE	Cut	81.00 FS	*80.80 FS
40	1		*LOCK CARRIER	Cracked	854.00 FS	*853.50 FS
41	1		*A/C CONDENSER	Not Necessary	586.00 FS	*- FS
42	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	627.00 FS	*- FS
43	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	503.00 FS	*- FS
44	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	574.00 FS	*- FS
45	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	22.00 FS	*- FS
46	1		*ADDITIONAL RADIATOR	Not Necessary	967.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*RADIATOR BRACKET -LH /RH UPPER	Not Necessary	92.00 FS	*- FS
48	2		*RADIATOR BUSH -LH/RH LOWER	Not Necessary	22.00 FS	*- FS
49	1		*RADIATOR	Not Necessary	1,099.00 FS	*- FS
50	6		*READY -MIX COOLANT	Necessary	326.00 FS	*325.20 FS
51	1		*RADIATOR AIR GUIDE -RH	Cracked	31.00 FS	*30.40 FS
52	1		*RADIATOR AIR GUIDE SEAL -RH OUTER	Not Necessary	10.00 FS	*- FS
53	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	20.00 FS	*- FS
54	1		*AIR INLET COVER	Not Necessary	31.00 FS	*- FS
55	1		*RADIATOR AIR GUIDE	Not Necessary	60.00 FS	*- FS
56	1		*RADIATOR AIR GUIDE	Not Necessary	21.00 FS	*- FS
57	1		*WATER DRAINAGE HOSE	Not Necessary	38.00 FS	*- FS
58	1		*RADIATOR AIR GUIDE	Not Necessary	71.00 FS	*- FS
59	1		*AIR FILTER	Not Necessary	356.00 FS	*- FS
60	1		*AIR FILTER INTAKE MANIFOLD	Not Necessary	793.00 FS	*- FS
61	1		*FRONT THROTTLE VALVE CONTROL ELEMENT	Not Necessary	812.00 FS	*- FS
62	1		*CHARGE AIR COOLER	Not Necessary	872.00 FS	*- FS
63	1		*FRONT WINDOW SLOT SEAL CHROME TRIM STRIP -RH	Not Necessary	366.00 FS	*- FS
64	1		*FRONT WINDOW GUIDE CHROME TRIM STRIP -RH	Not Necessary	304.00 FS	*- FS
65	1		*FRONT NOISE INSULATION	Not Necessary	437.00 FS	*- FS
66	1		*FRONT FENDER END PLATE -RH	Repair	101.00 FS	*- FS
67	2		*FRONT ALUMINIUM RIM -LH/RH	Not Necessary	2,760.00 FS	*- FS
68	2		*FRONT ALUMINIUM RIM RUBBER VALVE -LH	Necessary	8.00 FS	*3.80 FS
69	1		*FRONT NUMBER PLATE	Not Necessary	150.00 FS	*- FS
70	1		*FRONT BUMPER ASSY	Torn	800.00 FS	*800.00 FS
71	1		*SUNDRIES	Necessary	500.00 FS	*56.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **31,823.00** **17,442.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR ,CHECK ELECTRICAL FANS AND CONTROL UNIT .PRESSURISE COOLING SYSTEM TO CARRY OUT VACUUM AND REGAS RENEW WHERE NECESSARY	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM .TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,BONNET AND RHS HEADLIGHT.TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT .TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	7,000.00	4,550.00
6	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER ,LHS FRONT FENDER ,RHS FRONT FENDER TOP SUPPORT ,BONNET ,HINGES AND RHS FRONT DOOR	New	5,000.00	3,600.00
7	TO RENEW BOTH FRONT RIMS .TO CARRY OUT WHEEL ALIGNMENT	New	320.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			14,902.00	11,012.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >