

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0140/2023/EQ
DATE : 6-Feb-23
WIP : 61570

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/2023

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG SIEW JOO
ADDRESS : 1 LENGKONG EMPAT
#11-01
SINGAPORE 417609
TELEPHONE : HP +65 98443438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPG22009893
VEHICLE NO : **SMP 1166 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 26/7/2019
ENGINE NO : CHZ C27818
CHASSIS NO : WAUZZZ8V7K1025599
MILEAGE : -
DATE IN : 2-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Jan-23
PLACE OF ACCIDENT : JALAN SENANG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. RENEW WHERE NECESSARY.	S/N \$ 1,400.00	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILTIAE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,000.00	
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, LHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, BONNET, HINGES AND RHS FRONT DOOR.	\$ 5,000.00	
TOTAL LABOUR CHARGES		: \$ 14,390.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW BOTH FRONT RIMS. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$	320.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 14,902.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 337.00	
2	FRONT BUMPER GUIDE SECTION - RH	1	\$ 46.00	
3	FRONT BUMPER FOAM FILLER PIECE	1	\$ 224.00	
4	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	
5	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 144.00	
6	AIR CONDITIONER STICKER	1	\$ 9.00	
7	CAUTION SIGN STICKER	1	\$ 17.00	
8	HORN LOW TONE - RH	1	\$ 225.00	
9	FRONT FENDER - RH	1	\$ 1,012.00	
10	FRONT FENDER RIVET	5	\$ 20.00	
11	FRONT FENDER ATTACHMENT PARTS	1	\$ 80.00	
12	FRONT FENDER BRACKET - RH CENTER	1	\$ 57.00	
13	FRONT FENDER BRACE	1	\$ 114.00	
14	FRONT FENDER BRACKET - RH REAR	1	\$ 38.00	
15	FRONT FENDER INSULATION - RH	1	\$ 51.00	
16	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 39.00	
17	FRONT WHEEL HOUSING LINER - RH	1	\$ 198.00	
18	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 99.00	
19	BONNET	1	\$ 3,412.00	
20	BONNET ATTACHMENT PARTS	1	\$ 182.00	
SUB TOTAL SPARE PARTS		:	\$ 7,278.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE - LH / RH	2	\$ 146.00	
22	BONNET EDGE PROTECTION	1	\$ 33.00	
23	BONNET STRIKER - RH	1	\$ 130.00	
24	BONNET LOCK	1	\$ 241.00	
25	BONNET CATCH HOOK	1	\$ 106.00	
26	BONNET CATCH HOOK	1	\$ 75.00	
27	BONNET BOWDEN CABLE - CENTER	1	\$ 67.00	
28	BONNET RELEASE CABLE COVER	1	\$ 12.00	
29	BONNET LOCK CABLE	1	\$ 87.00	
30	BONNET ENGINE SOUND ABSORBER	1	\$ 260.00	
31	FRONT PLENUM CHAMBER COVER	1	\$ 211.00	
32	BONNET SIDE SEAL - RH	1	\$ 51.00	
33	HEADLIGHT - RH	1	TBC	
34	HEADLIGHT POWER MODULE - RH	1	\$ 876.00	
35	HEADLIGHT HEAT SINK - RH	1	\$ 868.00	
36	HEADLIGHT CONTROL UNIT	1	\$ 643.00	
37	HEADLIGHT HOSE - RH	1	\$ 48.00	
38	LIFT CYLINDER - RH	1	\$ 165.00	
39	LIFT CYLINDER HOSE	1	\$ 81.00	
40	LOCK CARRIER	1	\$ 854.00	
SUB TOTAL SPARE PARTS		:	\$ 4,954.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	A/C CONDENSER	1	\$ 586.00	
42	A/C CONDENSER REFRIGERANT LINE	1	\$ 627.00	
43	A/C CONDENSER REFRIGERANT LINE	1	\$ 503.00	
44	A/C CONDENSER REFRIGERANT LINE	1	\$ 574.00	
45	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	
46	ADDITIONAL RADIATOR	1	\$ 967.00	
47	RADIATOR BRACKET - LH / RH UPPER	2	\$ 92.00	
48	RADIATOR BUSH - LH / RH LOWER	2	\$ 22.00	
49	RADIATOR	1	\$ 1,099.00	
50	READY-MIX COOLANT	6	\$ 326.00	
51	RADIATOR AIR GUIDE - RH	1	\$ 31.00	
52	RADIATOR AIR GUIDE SEAL - RH OUTER	1	\$ 10.00	
53	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 20.00	
54	AIR INLET COVER	1	\$ 31.00	
55	RADIATOR AIR GUIDE	1	\$ 60.00	
56	RADIATOR AIR GUIDE	1	\$ 21.00	
57	WATER DRAINAGE HOSE	1	\$ 38.00	
58	RADIATOR AIR GUIDE	1	\$ 71.00	
59	AIR FILTER	1	\$ 356.00	
60	AIR FILTER INTAKE MANIFOLD	1	\$ 793.00	
SUB TOTAL SPARE PARTS		:	\$ 6,249.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT THROTTLE VALVE CONTROL ELEMENT	1	\$ 812.00	
62	CHARGE AIR COOLER	1	\$ 872.00	
63	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH	1	\$ 366.00	
64	FRONT WINDOW GUIDE CHROME TRIM STRIP - RH	1	\$ 304.00	
65	FRONT NOISE INSULATION	1	\$ 437.00	
66	FRONT FENDER END PLATE - RH	1	\$ 101.00	
67	FRONT ALUMINIUM RIM - LH / RH	2	\$ 2,760.00	
68	FRONT ALUMINIUM RIN RUBBER VALVE - LH / RH	2	\$ 8.00	
69	FRONT NUMBER PLATE	S/N	\$ 150.00	
70	FRONT BUMPER ASSY	S/N	TBC	
71	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 24,791.00	
TOTAL LABOUR CHARGES		:	\$ 14,902.00	
GRAND TOTAL		:	\$ 39,693.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT