

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0140/2023/EQ  
DATE : 6-Feb-23  
WIP : 61570

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/2023

**ERGO Insurance Pte Ltd**

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG SIEW JOO  
ADDRESS : 1 LENGKONG EMPAT  
#11-01  
SINGAPORE 417609  
TELEPHONE : HP +65 98443438  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : DMPG22009893  
VEHICLE NO : **SMP 1166 K**  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI  
MODEL YEAR : 26/7/2019  
ENGINE NO : CHZ C27818  
CHASSIS NO : WAUZZZ8V7K1025599  
MILEAGE : -  
DATE IN : 2-Feb-23  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 23-Jan-23  
PLACE OF ACCIDENT : JALAN SENANG

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                              | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS                       |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                                                                                               | S/N \$ 360.00         |                                                  |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                                                                       | S/N \$ 350.00         |                                                  |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. RENEW WHERE NECESSARY.                                                            | S/N \$ 1,400.00       |                                                  |
| 4                           | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.                                                                                                                    | S/N \$ 280.00         |                                                  |
| 5                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 7,000.00           | <i>@700 x 5 = 3500 + 100</i><br><i>2450 4550</i> |
| 6                           | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, LHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, BONNET, HINGES AND RHS FRONT DOOR.                                                                                                                               | \$ 5,000.00           | <i>3600</i>                                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                             | <b>: \$ 14,390.00</b> |                                                  |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K**

| S/N                         | NATURE OF JOBS                                          |             | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------|-------------|----------------------|-------------------------------|
| 7                           | TO RENEW BOTH FRONT RIMS. TO CARRY OUT WHEEL ALIGNMENT. | S/N \$      | 320.00               | 280                           |
| 8                           | TO CARRY OUT DIAGNOSTIC CHECK.                          | S/N \$      | 192.00               |                               |
| <b>TOTAL LABOUR CHARGES</b> |                                                         | <b>: \$</b> | <b>14,902.00</b>     |                               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K**

|                              |                                                        |     | DAMAGED PARTS & PRICES |               |
|------------------------------|--------------------------------------------------------|-----|------------------------|---------------|
| S/N                          | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS       |
| 1                            | FRONT BUMPER CLOSING ELEMENT - RH <i>mis /</i>         | 1   | \$ 337.00              | <i>336.50</i> |
| 2                            | FRONT BUMPER GUIDE SECTION - RH <i>cu /</i>            | 1   | \$ 46.00               | <i>45.40</i>  |
| 3                            | FRONT BUMPER FOAM FILLER PIECE <i>X nn</i>             | 1   | \$ 224.00              |               |
| 4                            | FRONT BUMPER REINFORCEMENT BEAM <i>lt /</i>            | 1   | \$ 974.00              | <i>✓</i>      |
| 5                            | FRONT BUMPER REINFORCEMENT BEAM COVER <i>X nn</i>      | 1   | \$ 144.00              |               |
| 6                            | AIR CONDITIONER STICKER <i>X nn</i>                    | 1   | \$ 9.00                |               |
| 7                            | CAUTION SIGN STICKER <i>X nn</i>                       | 1   | \$ 17.00               |               |
| 8                            | HORN LOW TONE - RH <i>cu /</i>                         | 1   | \$ 225.00              | <i>224.50</i> |
| 9                            | FRONT FENDER - RH <i>lt /</i>                          | 1   | \$ 1,012.00            | <i>✓</i>      |
| 10                           | FRONT FENDER RIVET <i>lt /</i>                         | 5   | \$ 20.00               | <i>✓</i>      |
| 11                           | FRONT FENDER ATTACHMENT PARTS <i>? X nn</i>            | 1   | \$ 80.00               |               |
| 12                           | FRONT FENDER BRACKET - RH CENTER <i>lt /</i>           | 1   | \$ 57.00               | <i>56.10</i>  |
| 13                           | FRONT FENDER BRACE <i>? lt /</i>                       | 1   | \$ 114.00              | <i>✓</i>      |
| 14                           | FRONT FENDER BRACKET - RH REAR <i>de /</i>             | 1   | \$ 38.00               | <i>37.50</i>  |
| 15                           | FRONT FENDER INSULATION - RH <i>X nn</i>               | 1   | \$ 51.00               |               |
| 16                           | FRONT FENDER CLOSING ELEMENT - RH <i>? X nn</i>        | 1   | \$ 39.00               |               |
| 17                           | FRONT WHEEL HOUSING LINER - RH <i>de /</i>             | 1   | \$ 198.00              | <i>197.50</i> |
| 18                           | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X nn</i> | 1   | \$ 99.00               |               |
| 19                           | BONNET <i>lt /</i>                                     | 1   | \$ 3,412.00            | <i>✓</i>      |
| 20                           | BONNET ATTACHMENT PARTS <i>X nn</i>                    | 1   | \$ 182.00              |               |
| <b>SUB TOTAL SPARE PARTS</b> |                                                        | :   | <b>\$ 7,278.00</b>     |               |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K**

|                              |                                           |      | DAMAGED PARTS & PRICES |                 |
|------------------------------|-------------------------------------------|------|------------------------|-----------------|
| S/N                          | PARTS DESCRIPTION                         | QTY  | S/NETT                 | REMARKS         |
| 21                           | BONNET HINGE - LH / RH ? Xnn              | 2 \$ | 146.00                 |                 |
| 22                           | BONNET EDGE PROTECTION ✓                  | 1 \$ | 33.00                  | 32.80           |
| 23                           | BONNET STRIKER - RH ? Xnn                 | 1 \$ | 130.00                 |                 |
| 24                           | BONNET LOCK ? Xnn                         | 1 \$ | 241.00                 |                 |
| 25                           | BONNET CATCH HOOK ? Xnn                   | 1 \$ | 106.00                 |                 |
| 26                           | BONNET CATCH HOOK ? Xnn                   | 1 \$ | 75.00                  |                 |
| 27                           | BONNET BOWDEN CABLE - CENTER ? Xnn        | 1 \$ | 67.00                  |                 |
| 28                           | BONNET RELEASE CABLE COVER ? Xnn          | 1 \$ | 12.00                  |                 |
| 29                           | BONNET LOCK CABLE ? Xnn                   | 1 \$ | 87.00                  |                 |
| 30                           | BONNET ENGINE SOUND ABSORBER Xnn          | 1 \$ | 260.00                 |                 |
| 31                           | FRONT PLENUM CHAMBER COVER ? Xnn          | 1 \$ | 211.00                 |                 |
| 32                           | BONNET SIDE SEAL - RH ? Xnn               | 1 \$ | 51.00                  |                 |
| 33                           | HEADLIGHT - RH bo/                        | 1    | TBC                    | 6232.00         |
| 34                           | HEADLIGHT POWER MODULE - RH short X short | 1 \$ | 876.00                 | 875.50          |
| 35                           | HEADLIGHT HEAT SINK - RH ? short          | 1 \$ | 868.00                 | ✓               |
| 36                           | HEADLIGHT CONTROL UNIT short              | 1 \$ | 643.00                 | ✓               |
| 37                           | HEADLIGHT HOSE - RH ? cut                 | 1 \$ | 48.00                  | 47.90           |
| 38                           | LIFT CYLINDER - RH car                    | 1 \$ | 165.00                 | 164.50          |
| 39                           | LIFT CYLINDER HOSE at                     | 1 \$ | 81.00                  | 80.80           |
| 40                           | LOCK CARRIER ? car                        | 1 \$ | 854.00                 | 853.50          |
| <b>SUB TOTAL SPARE PARTS</b> |                                           | :    | <b>\$</b>              | <b>4,954.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K**

|                              |                                          |          | DAMAGED PARTS & PRICES |                 |
|------------------------------|------------------------------------------|----------|------------------------|-----------------|
| S/N                          | PARTS DESCRIPTION                        | QTY      | S/NETT                 | REMARKS         |
| 41                           | A/C CONDENSER ? Xnn                      | 1 \$     | 586.00                 |                 |
| 42                           | A/C CONDENSER REFRIGERANT LINE ? Xnn     | 1 \$     | 627.00                 |                 |
| 43                           | A/C CONDENSER REFRIGERANT LINE ? Xnn     | 1 \$     | 503.00                 |                 |
| 44                           | A/C CONDENSER REFRIGERANT LINE ? Xnn     | 1 \$     | 574.00                 |                 |
| 45                           | OUTSIDE TEMPERATURE SENSOR BRACKET ? Xnn | 1 \$     | 22.00                  |                 |
| 46                           | ADDITIONAL RADIATOR ? Xnn                | 1 \$     | 967.00                 |                 |
| 47                           | RADIATOR BRACKET - LH / RH UPPER ? Xnn   | 2 \$     | 92.00                  |                 |
| 48                           | RADIATOR BUSH - LH / RH LOWER ? Xnn      | 2 \$     | 22.00                  |                 |
| 49                           | RADIATOR ? Xnn                           | 1 \$     | 1,099.00               |                 |
| 50                           | READY-MIX COOLANT ? new                  | 6 \$     | 326.00                 | 325.20          |
| 51                           | RADIATOR AIR GUIDE - RH ? OK             | 1 \$     | 31.00                  | 30.40           |
| 52                           | RADIATOR AIR GUIDE SEAL - RH OUTER ? Xnn | 1 \$     | 10.00                  |                 |
| 53                           | RADIATOR AIR GUIDE - UPPER CENTRE ? Xnn  | 1 \$     | 20.00                  |                 |
| 54                           | AIR INLET COVER ? Xnn                    | 1 \$     | 31.00                  |                 |
| 55                           | RADIATOR AIR GUIDE ? Xnn                 | 1 \$     | 60.00                  |                 |
| 56                           | RADIATOR AIR GUIDE ? Xnn                 | 1 \$     | 21.00                  |                 |
| 57                           | WATER DRAINAGE HOSE ? Xnn                | 1 \$     | 38.00                  |                 |
| 58                           | RADIATOR AIR GUIDE ? Xnn                 | 1 \$     | 71.00                  |                 |
| 59                           | AIR FILTER ? Xnn                         | 1 \$     | 356.00                 |                 |
| 60                           | AIR FILTER INTAKE MANIFOLD Xnn           | 1 \$     | 793.00                 |                 |
| <b>SUB TOTAL SPARE PARTS</b> |                                          | <b>:</b> | <b>\$</b>              | <b>6,249.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K**

|                             |                                                                            |     |    | DAMAGED PARTS & PRICES |         |
|-----------------------------|----------------------------------------------------------------------------|-----|----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                                                          | QTY |    | S/NETT                 | REMARKS |
| 61                          | FRONT THROTTLE VALVE CONTROL ELEMENT <i>Xnn</i>                            | 1   | \$ | 812.00                 |         |
| 62                          | CHARGE AIR COOLER <i>Xnn</i>                                               | 1   | \$ | 872.00                 |         |
| 63                          | FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH <i>Xnn</i>                   | 1   | \$ | 366.00                 |         |
| 64                          | FRONT WINDOW GUIDE CHROME TRIM STRIP - RH <i>Xnn</i>                       | 1   | \$ | 304.00                 |         |
| 65                          | FRONT NOISE INSULATION <i>? Xnn</i>                                        | 1   | \$ | 437.00                 |         |
| 66                          | FRONT FENDER END PLATE - RH <i>repair Xnn</i>                              | 1   | \$ | 101.00                 |         |
| 67                          | FRONT ALUMINIUM RIM - LH / RH <i>cut / LH - Subject to report</i>          | 2   | \$ | 2,760.00 <i>XNN</i>    |         |
| 68                          | FRONT ALUMINIUM RIN RUBBER VALVE - LH / RH <i>(R) LH subject to report</i> | 2   | \$ | 8.00 <i>3.80</i>       |         |
| 69                          | FRONT NUMBER PLATE <i>? Xnn</i>                                            | S/N | \$ | 150.00                 |         |
| 70                          | FRONT BUMPER ASSY <i>turn</i>                                              | S/N |    | TBC <i>800</i>         |         |
| 71                          | SUNDRIES <i>? nu</i>                                                       |     | \$ | 500.00 <i>56</i>       |         |
| <b>TOTAL SPARE PARTS</b>    |                                                                            |     |    | <b>: \$ 24,791.00</b>  |         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                            |     |    | <b>: \$ 14,902.00</b>  |         |
| <b>GRAND TOTAL</b>          |                                                                            |     |    | <b>: \$ 39,693.00</b>  |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

*Pass - Hg 90010068  
68/02/23 @ 1030  
8 days  
EXCESS: TBA  
Reveal  
Resurvey before paint*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT