# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

: 8

Attn: Sherini Pillai Date: 02 Aug 2023

## **Preliminary Advice**

Vehicle No : SLE3622S Accident Date : 22/01/2023

Make : TOYOTA COROLLA ALTIS Policy No. : D20MFL0000326 02

Date of Inspection : 06/02/2023 Est. Duration of Repair

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

205 BRADDELL ROAD SINGAPORE 579701

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,801.82
Revised Amount	:S\$	9,583.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,583.95
Lump Sum Repair	:S\$	7,650.00

#### **Total Loss Consideration**

New for Old Value	:S\$
New IOI Old Value	.01

 Pre-Accident Value
 :S\$ 57,000.00

 COE / PARF Rebate
 :S\$ 27,968.00

Salvage Value :S\$

Margin for Repair :S\$ 29,032.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage	је.
	Kindly let us have your authorisation.	

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.