Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

> 64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Sherini Pillai 07 Feb 2023 Date:

Preliminary Advice

Vehicle No : SLE3622S **Accident Date** : 22/01/2023

Policy No. : D20MFL0000326 02 Make : TOYOTA COROLLA ALTIS

Assignment Date : 06/02/2023 Excess : S\$0.00 Date of Inspection : 06/02/2023 Est. Duration of Repair : 8

: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) Inspection At

> 205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,016.27
Revised Amount	:S\$	9,156.45
Check Items (Estimated)	:S\$	486.90
Total	:S\$	9,643.35

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 57,000.00 COE / PARF Rebate 27,968.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 29,032.00

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject (x)to part prices and labour cost check.