Attn:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

: 8

Sherini Pillai Date: 27 Jul 2023

Preliminary Advice

Vehicle No : SLE3622S Accident Date : 22/01/2023

Make : TOYOTA COROLLA ALTIS Policy No. : D20MFL0000326 02

: 06/02/2023 Excess : S\$750.00 Assignment Date

Est. Duration of Repair Date of Inspection : 06/02/2023

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

> 205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,801.82 (inclusive supp \$785.55)
Revised Amount	:S\$	9,822.15
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,822.15
Lump Sum Repair	:S\$	7,850.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 57,000.00 COE / PARF Rebate :S\$ 27,968.00

Salvage Value :S\$

Margin for Repair :S\$ 29,032.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approve on supplementary.