

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCY/LA C23001237/UPA3

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM9223B

at Workshop m/s

Sin Hm

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$90k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

L1A 36225

Date / Time

Action / Instruction

13/2/23 1/5 1600 Des 12h: hand MR 60H

Veh No:

SM9223B

Yr Regn:

23/10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Hyundai

130

c.c

1353

Colour:

wh-te

A/C:

Insured / Std / NI / NA

Sp. Reading

48718

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TMAH3513VLJ115231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

01/01/23

D.O.I.

7/2/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

# SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59  
SINGAPORE 408717  
UEN: 201327079M

## Estimate

| Date     | Estimate # |
|----------|------------|
| 7/2/2022 | 1024       |

|                |
|----------------|
| Name / Address |
| NG SAING HUAT  |

not Arthur  
7/2/22  
1/4 # 1600 /  
3 days  
Wing we are rep

| VEHICLE NO | MODEL       |
|------------|-------------|
| SMP 9223 B | HYUNDAI I30 |

| Description                                                                      | Qty | Rate    | Total    |
|----------------------------------------------------------------------------------|-----|---------|----------|
| REAR BUMPER <i>deep cut</i>                                                      |     | 985.22  | 985.22   |
| REAR BUMPER SIDE RETAINER <i>ner</i>                                             |     | 35.74   | 35.74    |
| WHEEL BEARING <i>11</i>                                                          |     | 387.45  | 387.45   |
| KUNCKLE ARM <i>11</i>                                                            |     | 467.00  | 467.00   |
| MUD FLAG <i>5mm</i>                                                              |     | 65.74   | 65.74    |
| SUBTOTAL                                                                         |     |         | 1,941.15 |
| LESS 20%                                                                         |     | -388.23 | -388.23  |
| BUMPER CLIP <i>ner</i>                                                           | 10  | 4.50    | 45.00    |
| SPORT RIMS <i>cut</i>                                                            |     | 450.00  | 450.00   |
| COMPUTERIZED ALIGNMENT                                                           |     | 80.00   | 80.00    |
| TO REPLACE AND ALIGN REAR BUMPER TO SYSTEMICAL SPEC INCLUDE KNOCKING AND HEATING |     | 550.00  | 550.00   |
| TO SPRAY PAINT REAR BUMPER AND FENDER                                            |     | 650.00  | 650.00   |
| TO REPLACE REAR KUNCKLE ARM AND WHEEL BEARING                                    |     | 450.00  | 450.00   |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Total

\$3,777.92

1-1086.7  
202  
869.36