

Vehicle Damage Assessment Report for [SLA6512C]

Estimate Created: 09/03/2023 14:23 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 09/03/2023 14:44 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SLA6512C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- TOYOTA COROLLA ALTIS	Insurlogic 4 (09/03/2023 14:44)
- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$5,400.00 WITH 7 WORKING DAYS	Insurlogic 4 (09/03/2023 14:44)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
front bumper		1	481.60	-25.00 %	361.20
RH front bumper side holder		1	34.20	-25.00 %	25.65
front bumper logo		1	48.90	-25.00 %	36.68
RH headlamp		1	543.90	-25.00 %	407.93
RH front fender		1	595.40	-25.00 %	446.55
RH front fender inner cowling		1	168.90	-25.00 %	126.68
RH front lower arm		1	375.70	-25.00 %	281.78
RH front knuckle arm		1	516.40	-25.00 %	387.30
RH front wheel bearing hub		1	130.90	-25.00 %	98.18
RH front door		1	1141.30	-25.00 %	855.98
RH front door protector		1	131.40	-25.00 %	98.55
RH front door protector chrome moulding		1	32.80	-25.00 %	24.60
RH rear door		1	1089.40	-25.00 %	817.05
RH rear door protector		1	139.40	-25.00 %	104.55
RH rear door protector chrome moulding		1	30.90	-25.00 %	23.18

Parts Subtotal 4,095.86

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
front bumper clips		1.0	30.00	0.00 %	30.00
RH front fender inner cowling clips		1.0	30.00	0.00 %	30.00
RH front wheel rim		1.0	400.00	0.00 %	400.00
RH front door black tape		1.0	50.00	0.00 %	50.00
RH rear door black tape		1.0	50.00	0.00 %	50.00

Materials Subtotal 560.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To check wiring and light connect	RnR	30.00	0.00 %	30.00
Panel beating	RnR	800.00	0.00 %	800.00
Tuft coat	RnR	60.00	0.00 %	60.00
To transfer front and rear door fitting.	RnR	160.00	0.00 %	160.00

To dismantle front undercarriage.	RnR	180.00	0.00 %	180.00
To perform wheel alignment	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray painting	Full spray	800.00	0.00 %	800.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	1,310.00
			Paint Labor Subtotal	800.00
			Labor Subtotal	2,110.00

Summary

Repair Cost	6,765.86
Discount(20 %)	(1,353.17)
	5,412.69
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,412.69