

SLA 6512C.

Toyota Altis 1598cc

MROS3ZEE106153505

TP Ergo.

Hui Rong.

Front Bumper	Deformed	481.60	✓
Front Bumper Clips.	New	30(SN).	✓
Front Bumper Side Holder RH.	Damaged	34.20.	✓
Front Bumper Logo	New	48.90.	✓
Headlamp RH.	At	543.90	✓
Front RH Fender	Dented	595.40.	✓
Front RH Fender Inner Shield	Deformed	168.90	✓
Front RH Fender Inner Shield Clips.	New	30(SN)	✓
Front RH Wheel Rim.	At	850(SN) 400(SN)	
Front RH Tyre.	ATP New	280(SN)	X
Front RH lower Arm.	Bent	375.70.	✓
Front RH Shock Absorber.	ATP New	381.90	X.
Front RH Knuckle Arm.	Damaged	516.40.	✓
Front RH Wheel Hub c/w Bearing.	Damaged	130.90	✓

SLA 6512C

Front RH Anti-Roll Bar Linkage	NH Nec	96.90. +
Front RH Door Dented		1141.30. /
Front RH Door Lock	} XRP Nec	321.40. X
Front RH Door Weatherstripe.		278.80. X
Front RH Door Protector. Nec		131.40. /
Front RH Door Protector Chrome Moulding.	Nec	32.80. /
Front RH Door Black Tape.	Nec	50(SN). /
Rocker Panel Outer Garnish. R/R		655.30. X
Rocker Panel Outer Garnish Clips.	XRP Nec	80(SN) X
Rear RH Door. Dented.		1089.40. /
Rear RH Door Weatherstripe.	NH Nec	260.90. X
Rear RH Door Protector	Nec	139.40. /
Rear RH Door Protector Chrome Moulding.	Nec	30.90. /
Rear RH Door Black Tape.	Nec	50(SN) /

SLA 651.10

S.N. 560

Less 25% : 4095.82

SLA 6512C

Panel Beating	1200 800
Spray Painting.	1200 800
Wiring.	50 30
To apply tuff coat.	150 60
To transfer front and rear door fittings.	300 160
To dismantle front undercarriage.	350 180
To perform wheel alignment.	150 80

2110

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 6765.82

r/s: S.H.K.

07 Days.