



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 357A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BADLY DENTED	885.40	885.40
1	TAILGATE INNER LOCK	TWISTED / JAMMED	131.60	131.60
1	TAILGATE LOGO -JAZZ	NECESSARY	21.30	21.30
1	REAR BUMPER	DENTED	529.90	529.90
1	REAR BUMPER RETAINER RH	NOT NECESSARY	17.00	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	17.00	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	118.30	118.30
4	REAR BUMPER CLIP @\$3.80	NOT NECESSARY	15.20	-
1	END PANEL	BADLY DENTED	399.60	399.60
1	REAR BUMPER TOP GARNISH	TWISTED	65.60	65.60
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	697.00	-
1	REAR FENDER LAMP RH	NOT NECESSARY	271.90	-
1	REAR FENDER LAMP LH	NOT NECESSARY	271.90	-
	LESS 20% DISCOUNT		-688.34	-430.34
			2,753.36	1,721.36
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (SN)	SHORTED	560.00	200.00
2	WINDSCREEN SEALANT @\$24.00 (SN)	NECESSARY	48.00	40.00
1	REAR FENDER RH(NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH(NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			608.00	240.00
<u>LABOUR</u>				
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL ,REAR FENDER RH AND REAR FENDER LH.		1,200.00	800.00
	SPRAY PAINT ON THE AFFECTED AREAS .		1,100.00	800.00
	ANTI -RUST COATING. (NPA)	NOT NECESSARY	-	-
	TO REMOVE & REFIT WINDSCREEN.		180.00	120.00

Report Ref No. CS/AGI23001241/Uqy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REVERSE SENSOR .		150.00	50.00
			2,630.00	1,770.00
GRAND TOTAL			5,991.36	3,731.36
RECOMMENDED COST OF REPAIR SUM				3,350.00

Report Ref No. CS/AGI23001241/Uqy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.