



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23001244/y3 Date: 06/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 1716 L	Veh. Inspected	SH 9866S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2300472/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/02/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	02/02/2023	Inspection Date	
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			