	23001244/kgy3
Kenneth	ASSIGNMENT
From: Date:	Veh No: SH 9865 Yr Regn: OF 21
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry Taxl / Prime Mover /
OD VIP WS I TP RES I OD RES I EVA / INV I MY	Truck / Trailer or
To Inspect Vehicle No:	11
at Workshop m/s Bi Broy	Colone Lonia co 1500
of	Consumed / Std / NI / NA
Insured:	Sp.Reading 186489 T/Radio: Insured / Std / N1 / NA
Policy No.	Eng/No:
Claims No.	C/No: KMITC851CV & U 193116
Sum Insured: Excess:	Gen. Cond: 800d / Fair / Poor / Burnt
(Cfient's Record)	Steering: Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingrder / Jammed / Leaked / Burnt or
	Modi: Nil / S/RIm / STO A/Rim or
(Policy Condition)	Tyre Size: F: 185/65R15
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	HANKOOK HANKOOK
IDAC Accident Rport: Consistent? : Yes or No	<u>Front</u> <u>Rear</u>
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 9 mm R/Bal. 9 mm
Est. Repairs: C6 days Res.: Yes or No	L/Bal. 9 mm L/Bal. 9 mm
Lum Sum: 1. B./% 3 Val.: Yes or No	D.O.A. 2/2/23 D.O.I. 7/2/2023
7 Tall. 163 Of 140	Survey held at 3.26
CA / REV / REP. / 24 HRS	Des. of Damages : Frt   Rear   O/S   N/S   U/C   Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Teller journel	
0	
2915 \$13003.08 Call Red	\$ 9888.18, 43/2)
u.	
Onto/Timo, File Pass to?	
D. Prell. Report	ays Of Repair:
10/10 10/40   I Flant D	OSUDION No. of T. I.
A CALCULA IO	
Add Fee:	: Site Insp (\$ )s - Rssi
TP TP	: Interview (\$
Report Format :	Tech Invs (\$ ) Others
ump Stim / I.B.I: (\$ 13003.08)	Weekend (\$
_	In the control of the
,	ICTAL

# **BIFROST AUTO PTE LTD**

Not Norther as Resurry B4 pains Eday, \$13003.08

## **REPAIR ESTIMATE**

DATE:

7-Feb-23

INSURANCE:

MODEL:

HYUNDAI IONIC

**VEHICLE NO.:** 

SH 9866 S

Description	e =	Qty	l is	st Price	Amount	1
	4	1		2,549.70	\$ 2,549.70	
Boot Lid Rubber	Dr	1	\$	187.40	\$ 187.40	2
Boot Lid Hinge (LH/RH)	7	2	\$	71.30	\$ 142.60	X
Boot Lid Absorber (LH/RH)	2	2	\$	86.70	\$ 173.40	X
Boot Lid Lock Upper	Per	1	\$	224.00	\$ 224.00	2
Boot Lid 'H' Emblem	4	1	\$	28.00	\$ 28.00	
Emblem-Hybrid	4	1	\$	24.30	\$ 24.30	_
Emblem-loniq	2	1	\$	31.30	\$ 31.30	
Rear Spoiler	gn	1	\$	665.40	\$ 665.40	X
Third Brake Light	'n	1.,	\$	385.60	\$ 385.60	X
DOOTTIVATELL	Su	1	\$	31.80	\$31.80	X
Boot Lid Lamp(LH/RH) Ws Sut alsom		2	\$	822.00	\$ 1,644.00	4
Boot Lid Trimboard		1	\$	259.70	\$ 259.70	2
Boot Lid Trimboard,Centre	h	1	\$	159.60	\$ 159,60	×
	n	2	\$	92.50	\$ 185.00	X
Boot Lid Trimboard REAR	Ph	1	\$	124.80	\$ 124.80	X
Boot Lid Glass Upper Moulding	nn	1	\$	186.30	\$ 186.30	X
Boot Lid Glass Lower Moulding	n	1	\$	145.20	\$ 145.20	X
Rear Bumper	R	1	\$	459.40	\$ 459.40	_
Rear Bumper Reinforcement	Ry	1	\$	394.80	\$ 394.80	_
Rear Bumper Reinforcement Bracket (LH/RH)	1	2	\$	188.10	\$ 376.20	4.
Antenna Assy-SMARTK outer	201	1	\$	689.50	\$ 689.50	2
Rear Bumper Centre Moulding Assy	RI	1	\$	451.25	\$ 451.25	_
Rear Bumper Lower Centre Moulding Assy	CM	1	\$	155.00	\$ 155.00	

Rear Bumper Stay	DI	1	\$ 138.10	\$ 138.10	<u> </u>
Rear Bumper Side retainer (LH/RH)	ימ	7 2	\$ 85.80	\$ 171.60	
Rear Bumper Cover Clips	Ma	1	\$ 22.00	\$ 22.00	
Rear Bumper Side Under(LH/RH)	cm	2	\$ 123.10	\$ 246.20	2
Rear Bumper Rear Hook	Sz	1	\$ 94.60	\$ 94.60	X
Rear Bumper Reflector Lamp(LH/RH)	cm	2	\$ 82.90	\$ 165.80	at RI
Rear Bumper Towing Cover	ru	1	\$ 98.80	\$ 98.80	X
Rear Bumper Reserve Light (Parking Brake Ligh	nt) Mi	1	\$ 328.60	\$ 328.60	
Licence Lamp	Su	1	\$ 193.53	\$ 193.53	X
Tail Lamp(LH/RH)	als by	2	\$ 935.40	\$ 1,870.80	it
Tail Lamp Quarter Panel(LH/RH)	n	2	\$ 208.90	\$ 417.80	X
Rear Panel	B	1	\$ 532.00	\$ 532.00	
Antenna Assy - TRUNK	no	1	\$ 689.50	\$ 689.50	7
Rear Panel Garnish	Bu	1	\$ 346.80	\$ 346.80	
Spare Tyre Holder	Su	1	\$ 223.10	\$ 223.10	X _
Spare Wheel Lock Nut	R	1	\$ 89.50	\$ 89.50	1
Spare Tyre Panel	n	-1-	\$ 892.50	\$ 892.50	X
Spare Tyre Panel Cushion	Su	1	\$ 692.50	\$ 692.50	X
Rear tray tools box RH	<i>In</i>	1	\$ 675.30	\$ 675.30	X
Rear tray tools box LH	cm	1	\$ 693.20	\$ 693.20	
REAR TRAY LUGGS CENTER	Palp	71.	\$ 354.20	\$ 354.20	
Assy BSD Blind Spot Radar (LH)	Rel	1	\$ 1,784.40	\$ 1,784.40	2
S	UB TOTAL			\$ 20,395.08	
*	LESS 20%			\$ 4,079.02	
DISCOUNT	ED TOTAL			\$ 16,316.06	
Reverse camera ASSY	In SN	1	\$ 983.20	\$983.20	Х
Boot Lid Comfort Logo & Tel No. Sticker	re SN	1	\$ 35.00	\$ 35.00	
Rear No.Plate + Trim Cover	CM SN	1	\$ 45.00	\$ 45.00	
Rear Windscreen Sealant	M SN	2	\$ 46.00	\$ 92.00	form 3am
Rear Bumper Rubber Mat	M SN	1	\$ 50.00	\$ 50.00	SOL
Rear Bumper Reverse Sensor	hay SN	1	\$ 180.00	\$ 180.00	
SPARE TYRE PANEL TOP COVER SILICON	NN SN	1	\$ 250.00	\$ 250.00	×

T.

SUB TOTAL	+		\$ 1,635.20
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,400.00	\$1,400.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge (Bill	1)1	\$80.00	\$80.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	\$550.00
TOTAL LABOUR			\$4,940.00
ESTIMATE TOTAL			\$22,891.26

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims\_ltr@bifrostauto.com

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	licie
Owner ID Type:	Company
Owner ID: Vehicle Details	821R
Vehicle No.:	SH9866S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Feb 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU422240
Chassis No.:	KMHC851CVLU193118
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,219.00
Original Registration Date:	28 Jul 2021
First Registration Date:	28 Jul 2021
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2029
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00
COE Expiry Date:	27 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,517.00
COE Rebate Amount:	\$30,013.00
Total Rebate Amount:	\$33,763.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Feb 2023

Message





1 of 3 Report No. T/20230202/2090

Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827

Tel No: 1800-8529999

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/02/2023 18:39			Vide Report No.:	Station Diary No.: 91		
Informan	t's Particu	ılars				
Name of I LEOW CH	nformant: HOR KIM		Address: APT BLK 706 YISHUN AVEN 760706	IUE 5 #06-186 SINGAPORE		
ID Type / ID No.: NRIC NO / S1664787Z			Contact No.: Home/Office: Mobile: 97689649			
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Female	Age: 58	Date of Birth: 01/12/1964	Type of Informant: Driver			
Race: Chinese			Language:	Institution / School Name:		
Occupation: Taxi driver			Driving Licence Information: Class:	Date of Expiry:		

General Inform	nation of the Accident				
Type of Accident: Injury Conveyed By Ambular		Drink Drive: No	Date/Time of Accident: 02/02/2023 13:10	Type of Location: T-Junction	
Location:					
YISHUN AVE	NUE 4				
Weather:	Ro	ad Surface:		Road Speed Limit:	
Clear Dry					
Traffic Flow:	Tra	ffic Control:		Traffic Volume:	
One Way	Tra	ffic Light - Wo	orking	Light	
Type of Collis	sion: ring Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE1716L	Van				Slightly Damaged	0
SH9866S	Car				Slightly Damaged	2





Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

2 of 3 Report No. T/20230202/2090

CONTINUATION OF REPORT

#### Brief Details.

On 02/02/2023 at about 1310hrs, I was driving along Avenue 4 at the traffic light T junction on my right is street 81 and on my left is towards Avenue 1. When the traffic light ahead of me turn red and I stop my Taxi when a Van crashed into my Taxi from the rear. Subsequently I felt giddy in my head and call for ambulance my 2 passengers and I were conveyed to knoo teck puat hospital. The rear bumper of my taxi came out. There was in car camera in my Taxi. I was discharged from Hospital and was given 5 days of MC and 5 days of light duties.





3 of 3

Report No. T/20230202/2090

Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

CONTINUATION OF REPORT

### Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: L / SGT 2 CHEW JING HUI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/02/2023 18:39
Officer In Charge Of Case: TP / GIT / SGT 3 MUHAMMAD SYAKIR BIN ADANAN Contact No.: 65476236	Classification Of Case: