

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0157/2023/EQ
DATE : 8-Feb-23
WIP : 62102

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SLQ 2971 L**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ANDREW POH KENG JOO
ADDRESS : 24 GLASGOW ROAD
#04-08
SINGAPORE 549340
TELEPHONE : HP +65 93832482
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070005184-01
VEHICLE NO : **SMR 8175 C**
MODEL CODE : AUDI A1 SB ADVANCED 1.0 T
MODEL YEAR : 23/1/2020
ENGINE NO : DKJ 046042
CHASSIS NO : WAUZZZGB8LR008840
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Feb-23
PLACE OF ACCIDENT : LIVIA CONDO CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8175 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	x.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	x.
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	500
4	TO RESPRAY FRONT BUMPER.	\$	900.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	/
TOTAL LABOUR CHARGES		:	\$ 2,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8175 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rev</i>	1	\$ 1,839.00	+	
2	FRONT BUMPER FIXING PARTS	1	\$ 151.00	+	
3	FRONT BUMPER SPOILER - RH	1	\$ 119.00	+	
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	1	\$ 249.00	✓	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 198.00	+	
6	FRONT BUMPER GUIDE PROFILE - RH	1	\$ 43.00	+	
7	FRONT BUMPER GUIDE SECTION - RH <i>NP</i>	1	\$ 127.00	+	
8	HEADLIGHT - RH <i>NK</i>	1	\$ 4,830.00	+	
9	LIFT CYLINDER - RH	1	\$ 165.00	+	
10	LIFT CYLINDER HOSE	1	\$ 71.00	+	
11	RADIATOR AIR GUIDE - RH	1	\$ 53.00	+	
12	SUNDRIES		\$ 400.00	+	
TOTAL SPARE PARTS			\$ 8,245.00		
TOTAL LABOUR CHARGES			\$ 2,852.00		
GRAND TOTAL			\$ 11,097.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Ling
28/02/23.

not authorised, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT