

Vehicle Damage Assessment Report for [SHC1356G]

Estimate Created: 07/02/2023 02:33 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 12/05/2023 14:45 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SHC1356G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,450.00 WITH 2 WORKING
DAYS

Insurlogic 4 (12/05/2023 14:42)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RH rear door panel sub assy		1	1258.30	-25.00 %	943.73
RH Rear door comfort apps logo		1	80.00	0.00 %	80.00
Renew advertisement sticker		1	100.00	0.00 %	100.00

Parts Subtotal 1,123.73

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
OD/TP Case (Insurer)		1.0	11.00	0.00 %	11.00

Materials Subtotal 11.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	350.00	0.00 %	350.00
Transfer of door	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	250.00	0.00 %	250.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 400.00

Paint Labor Subtotal 250.00

Labor Subtotal 650.00

Summary

Repair Cost 1,784.73

Discount(20 %) (356.94)

1,427.79

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 1,427.79