



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Choo Chwee Har 501 Sembawang Road #04-07 Singapore 757706 Mobile: 92766269		
			Document No.				
			0				
			Document Date				
			06/02/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZRE210R	GEXGPZ C1	29/10/2020	SFD1169Z	0	20051	SFD1169Z
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2BE3BE800011048		1ZR0F65453	60	Thomas Pang W T	--/--/----		0.00
							0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI TP INS: TP VEH:YP4570P DATE OF ACC:03.02.2023				100.00	
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00	
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				134.64	
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				1584.00	
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1312.00	
7	1	SPC507-12005 17 BACK SENSOR (1D4, SILVER METAL	1.00	190.00		190.00	
8	2	S52159-0Z961 COVER, RR BUMPER L/C	1.00	639.80		639.80	
9	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.90		49.00	
10	4	S52023-02240 REINFORCEMENT SUB-AS	1.00	399.90		399.90	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							4,805.34
			Please acknowledge receipt of vehicle				GST 8.00%
							384.43
			Parts		1,278.70		
			Labour		3,526.64		
			Sublet		0.00		
			Lubrication/Fluid		0.00		Less
			Others		0.00		0.00
							Amount Due
							5,189.77

Customer Copy