

ASS. REC. BY:

REF:

LPC / 23001269/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

EM not ready

22/2 LRP 84300 Car

Veh No:

WWC 8399

Yr Regn:

01, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Hiac

c.c

2494

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

353696

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PN1150 2P204 008827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

5

mm

L/Bal.

9

mm

L/Bal.

5

mm

D.O.A.

8/2/23

D.O.I.

8/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

F. m. s.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TSR AUTOMOTIVE PTE LTD
 160, SIN MING DRIVE, SIN MING AUTOCITY
 # 06-15 SINGAPORE 575722
 EMAIL : tsrteamworks2022@gmail.com . H.P 90030857 .

Not Notch in
11 Sep & 4300h
Mercury After Paint
5 days

Date : 8 Feb 2023

QUOTATION - THIRD PARTY CLAIM

LONPAC INSURANCE BHD
 DATE ACCIDENT : 6 Feb 2023

CLAIM : THIRD PARTY CLAIM
 VEH. No : WWC 8399 / HIACE

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : ALLIANZ GENERAL

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : GBF 6911 B			
1	TAILGATE	\$ 1,850.00	✓
1	TAILGATE W/SCREEN MOULDING	\$ 180.00	X
1	TAILGATE WEATHERSTRIP	\$ 285.00	50% in
1	TAILGATE TRIM BOARD	\$ 322.00	X
1	TAILGATE CENTER LOGO	\$ 68.00	✓
1	TAILGATE OUTER GARNISH	\$ 380.00	X
1	TAILGATE LOCK	\$ 465.00	✓
1	TOYOTA STICKER	\$ 165.00	X
1	HIACE STICKER	\$ 165.00	✓
2	TAILLAMPS	\$ 798.00	✓
2	TAILLAMP LOWER BRACKETS	\$ 280.00	X
2	TAILLAMP PANELS	\$ 480.00	X
2	REAR SIDE PANELS	REPAIR	
1	REAR BUMPER	\$ 580.00	✓
2	REAR BUMPER BRACKETS	\$ 228.00	X
2	REAR BUMPER SIDE STAYS	\$ 180.00	X
1	REAR EXHAUST	\$ 685.00	X
1	SPARE TYRE BRACKET 376.30	\$ 480.00	✓
1	END PANEL	\$ 552.00	✓
1	END PANEL TOP METAL STRIP 198	\$ 330.00	✓
1	END PANEL TOP LATCH	\$ 68.00	X
1	FLOOR PANEL	REPAIR	
TOTAL PARTS :		\$ 8,541.00	
LESS 25%		\$ 2,135.25	
TOTAL LIST PARTS :		\$ 6,405.75	
SPECIAL / NETT PARTS			
2T	REAR W/SCREEN SEALANT	\$ 120.00	40% in
1SET	REVERSE SENSOR	\$ 300.00	200% in
1	REAR No. PLATE WITH FRAME	\$ 50.00	X
1	SPARE TYRE	\$ 600.00	50% in 100% in
TOTAL S/N PARTS :		\$ 1,070.00	
TOTAL PARTS PRICE :		\$ 7,475.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

AMOUNT BRING FORWARD :	\$	7,475.75
------------------------	----	----------

REAR LABOUR CHARGES

Labour charges to do cutting , welding repair replace rear accident affected area	\$	1,200.00	600
To remove refix rear w/screen	\$	140.00	120
To transfer tailgate parts to another tailgate	\$	120.00	60
To do rear chassis body alignment	\$	nn 350.00	X
To do anti rust	\$	120.00	60
To seal gap, waterproofing on rear cutting welding , accident affected area	\$	250.00	30
To replace rear exhaust	\$	nn 180.00	X
To remove refix , side trim, trim board, floor board etc	\$	280.00	60
To do spray painting on rear accident affected area	\$	1,000.00	700
TOTAL LABOUR :	\$	3,640.00	
GRAND TOTAL PARTS & LABOUR :	\$	11,115.75	



TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com . H.P 90030857 .

Date : 8 Feb 2023

QUOTATION - THIRD PARTY CLAIM

LONPAC INSURANCE BHD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 6 Feb 2023

VEH. No : WWC 8399 / HIACE

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : ALLIANZ GENERAL

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : GBF 6911 B			
4	REAR BUMPER LOWER BRACKETS	\$ <i>mit</i> 85.00	✓
2	REAR APRON PANEL	\$ <i>n</i> 280.00	X
1	REAR EXHAUST	REPAIR	
	TOTAL PARTS :	\$ 365.00	
	LESS 25%	\$ 91.25	
	TOTAL LIST PARTS :	\$ 273.75	
	SPECIAL / NETT PARTS		
1	REAR FLOOR PANEL TOP STEEL PLATE	\$ <i>sn</i> 600.00	X
	TOTAL S/N PARTS :	\$ 600.00	
	TOTAL PARTS PRICE :	\$ 873.75	

AMOUNT BRING FORWARD :	\$ 873.75
------------------------	-----------

REAR LABOUR CHARGES

Labour charges to repiar exhaust	\$ <i>nn</i> 60.00	X
TOTAL LABOUR :	\$ 60.00	
GRAND SUPPLEMENTARY PARTS & LABOUR :	\$ 933.75	