

ASS. REC. BY:

REF:

TV 1 230012701kp
GRB

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8521c

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKM 8873X Yr Regn: 04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 c.c. 1997

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 99238 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA WX 320100B 28378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 245/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 2/2/23 D.O.I. 7/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Vehicle from accident on 18/1/23.

2 2/2 / 1 Rm & 7200L Cabin

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06747

Vehicle Insured : SLQ3950G

Accident Date : 02-Feb-2023

Date : 06-Feb-2023

Our Ref : 023022 (III) / CHAN

PAGE : 1

FEI YING YING
22 FLORA DRIVE
#08-40
Singapore 506948

*NOT Notified
L1 Rep &
Resurvey After Paint
5 days*

ESTIMATED COST OF REPAIR FOR BMW X3 XDRIVE 20I SKM8873X

1 pc	Rear bumper fascia	<i>(1st)</i>	<i>Mc Bulet...</i>	1,589.65	<i>X</i>
2 pcs	Rear bumper towing cover	<i>(1st)</i>	@ S\$ 93.60	<i>Net</i> 187.20	<i>X</i>
2 pcs	Rear bumper ctr parking sensor		@ S\$255.65	<i>Per/mi</i> 511.30	<i>✓</i>
1 pc	Rear bumper centre pad	<i>(1st)</i>	<i>Mc (CMA)</i>	252.65	<i>X</i>
1 pc	Rear bumper centre pad gasnish		<i>mi</i>	93.40	<i>✓</i>
1 pc	Rear bumper lower cover		<i>mi</i>	128.25	<i>✓</i>
1 pc	Rear bumper reinforcement		<i>My</i>	854.50	<i>✓</i>
2 pcs	Rear bumper inner parts		@ S\$193.20 <i>CMA</i>	386.40	<i>✓</i>
1 pc	Rear end panel - lower		<i>My</i>	631.65	<i>✓</i>
1 pc	Rear end panel -top		<i>Sm</i>	856.95	<i>X</i>
1 pc	Tail gate		<i>My</i>	2,088.95	<i>✓</i>
1 pc	Rear exhaust heat seal		<i>Sm</i>	155.20	<i>X</i>
1 pc	Rear exhaust chrome pipe		<i>Net</i>	158.65	<i>✓</i>
1 pc	Rear exhaust mounting		<i>Sm</i>	38.15	<i>X</i>
				7,932.90	
Less 5% :				396.64	

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper rivet

Mc 7,536.26
For 60.00 sn
Mc 30.00 sn *✓*

To remove & refix rear windscreen
glass and conduct water leak test.

120
150.00

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *60*

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ3950G

Page : 2

To apply undersealing

300 80.00

To remove and renew exhaust
silencer box

60.00 *✓*

To putty and spray replaced parts

500 1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *600*

Total : S\$10,036.26
=====

Singapore Dollars Ten Thousand and Thirty Six
and Cents Twenty Six Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ3950G (INDIA)

Date : 10-02-2023

Accident Date : 02-02-2023

Our Ref : 023022 / CHAN

FEI YING YING

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR BMW X3 XDRIVE 20I SKM8873X

1 PC REAR EXHAUST BOX

B1 \$1,403.50 ✓

1 PC CENTRE EXHAUST PIPE

B1 \$1,334.50 ✓

2 PCS HEADREST AIR BAG @ \$162.55

Activator \$325.10 ✓

\$3,063.10

LESS 5% \$153.16

\$2,909.94

Singapore Dollars Two Thousand Nine Hundred Nine And Cents Ninety Four Only