

ASS. REC. BY:

REF:

C72/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.1B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9853 E

Yr Regn:

12 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Priv

c.c

1798

Colour

M.P. White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

206023

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J70K83FU 703093242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

26/1/23

D.O.I.

27/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S - RS. SI

) Fuel

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9853E

Not Notified
Phenny Bepart
@ 1611.68

AAD2301-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 JAN 2023**SHD9853E**

JTDKB3FU703093242

201603575K

TOYOTA

PRIUS GEN 4

26/01/2023

SKW7465U/CHINA

23/12/2020

PART

- 1 RIM
- 1 HUB CAP
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH

LIST

\$	<i>Pr</i>	1,995.11	X
\$	<i>nd/Pr</i>	222.08	✓
\$	<i>R</i>	1,099.46	X
\$	<i>Pr</i>	176.09	X
\$	<i>Pr</i>	612.68	✓
\$	<i>Pr</i>	27.93	X
\$	<i>Pr</i>	472.19	X
\$	<i>Pr</i>	49.25	X
\$	<i>Pr</i>	167.48	✓
\$	<i>Pr</i>	756.74	X

TOTAL \$ 4,822.27
25% \$ 1,205.57
\$ 3,616.70

Special Nett

- 1SET CLIP, ROCKER PANEL MOULDING
- 1SET BUMPER CLIP REAR
- 1SET REAR BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	65.00	<i>65.00</i>
\$	<i>nn</i>	85.00	X
\$	<i>nn</i>	130.00	X
\$	<i>nn</i>	65.00	X

TOTAL \$ 410.00
TOTAL PARTS \$ 2,300.00

LABOUR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2301-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9853E

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	300/
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	440/
To reinstall rear bumper parking sensor.	\$	170.00	50/
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	10/
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	11,016.70	

(PART-BY-PART) Repair Days

08 Days

3 day/