

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9853E

Not Notified
Resurvey B9 paint
@ 1611.68

AAD2301-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 JAN 2023**SHD9853E**

JTDKB3FU703093242

201603575K

TOYOTA

PRIUS GEN 4

26/01/2023

SKW7465U/CHINA

23/12/2020

PART

- | | |
|---|--------------------------------------|
| 1 | RIM |
| 1 | HUB CAP |
| 1 | PANEL SUB-ASSY, QUARTER, RH |
| 1 | LINER, REAR WHEEL HOUSE, RH |
| 1 | COVER, REAR BUMPER |
| 1 | COVER, REAR BUMPER, LOWER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | REFLECTOR ASSY, REFLEX, RH |
| 1 | REAR BUMPER SIDE RETAINER RH |
| 1 | MOULDING ASSY, BODY ROCKER PANEL, RH |

LIST

\$	<i>Pr</i>	1,995.11	X
\$	<i>nd/Pr</i>	222.08	✓
\$	<i>R</i>	1,099.46	X
\$	<i>Pr</i>	176.09	X
\$	<i>Br</i>	612.68	✓
\$	<i>Pr</i>	27.93	X
\$	<i>Pr</i>	472.19	X
\$	<i>Pr</i>	49.25	X
\$	<i>Di</i>	167.48	✓
\$	<i>Pr</i>	756.74	X
TOTAL	\$	4,822.27	
25%	\$	1,205.57	
	\$	3,616.70	

Special Nett

- | | |
|------|-----------------------------|
| 1SET | CLIP, ROCKER PANEL MOULDING |
| 1SET | BUMPER CLIP REAR |
| 1SET | REAR BUMPER RETAINER CLIP |
| 1SET | FENDER CLIP |
| 1 | FENDER LINER CLIP |

\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	<i>65.00</i>
\$	<i>na</i>	85.00	X
\$	<i>na</i>	130.00	X
\$	<i>na</i>	65.00	X
TOTAL	\$	410.00	

TOTAL PARTS \$ 2,300.00**LABOUR**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd**AAD2301-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9853E

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>3000</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>4400</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>500</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	5,100.00	
Over All Total	\$	11,016.70	

(PART-BY-PART) Repair Days~~08 Days~~*3 days*