LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

09 Feb 2023 Attn: Jenny Lew Date:

Preliminary Advice

Vehicle No : YQ3448L Accident Date : 05/02/2023

Make : MITSUBISHI CANTER Policy No.

DMCVSNW00053482201

: S\$350 00 Assignment Date : 07/02/2023 **Excess**

: 7/2/2023 Date of Inspection Est. Duration of Repair : 12

Inspection At :DING AUTO PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| :S\$ | 25,253.84 |
|------|--------------|
| :S\$ | 20,893.84 |
| :S\$ | 2,090.00 |
| :S\$ | 22,983.84 |
| | :S\$:S\$ |

Lump Sum Repair :S\$

Total Loss Consideration

| | and the second s |
|-------------------|--|
| New for Old Value | :S\$ |
| | |

Pre-Accident Value 85,000.00 :S\$ COE / PARF Rebate :S\$ 21,667.00

Salvage Value :S\$

Margin for Repair :S\$ 63,333.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let |
|-------|---|
| | us have your authorisation. |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Lump Sum repair

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.

Pending for investigation