

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Document no. 06-02-2023
Document date 5211001170
Customer no. 200208384E
Customer GST-ID 30001
Dealer 2023003349/ 1
Job order number 06-02-2023
Job order date Dass Anthonidas
Service Advisor Christopher

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms. ZHANG
XIAOTONG
BLK 138A YUAN CHING ROAD
#17-115
SINGAPORE 611138

License plate SMJ9634E	Model code NX34JDS1	First registration 07-01-2022	VIN TMBBR7NX4MY179745	Model OCTAVIA M-HEVSTY TS110/1.5A7F	Mileage 20
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES REPAIR				#6	280.00 <i>Xan</i>	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00 ✓	518.40
5E6807421	Rear Bumper <i>der</i>	1	pcs.	1,843.66	#6	1,843.66 ✓	1,991.15
5E7807441	Unbekannt <i>- tow tower Xan</i>	1	pcs.	28.10	#6	28.10	30.35
5E7807393	Unbekannt <i>Xan</i>	1	pcs.	48.60	#6	48.60	52.49
5E7807394	LHR BUMPER BRACKET (SIDE) <i>? Xan</i>	1	pcs.	48.60	#6	48.60	52.49
	Guide Profile RHS						
	RHR BUMPER BRACKET (SIDE) <i>? Xan</i>	1	pcs.	65.94	#6	65.94	71.22
5E6807377	Unbekannt	1	pcs.	65.94	#6	65.94	71.22
5E6807378	LHR BUMPER BRACKET (OUTER) <i>? Xan</i>	1	pcs.	65.94	#6	65.94	71.22
	Guide Profile						
	RHR BUMPER BRACKET (OUTER) <i>? Xan</i>	1	pcs.	84.22	#6	84.22	90.96
5E6807863	Unbekannt	1	pcs.	84.22	#6	84.22	90.96
	RR BUMPER BRACKET (CTR) <i>? Xan</i>	1	pcs.	625.49	#6	625.49	675.53
5E3807305D	Unbekannt <i>? Xan</i>	1	pcs.	625.49	#6	625.49	675.53
	REINFORCEMNT						
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64 ✓	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37 ✓	80.32
5WA919275B GRU	Sensor Primed <i>? Xan</i>	4	pcs.	194.63	#6	778.52	840.80
3Q0919133 9B9	Seal Ring Satin Black <i>? Xan</i>	4	pcs.	6.10	#6	24.40	26.35
5E7919485A	Sensor Bracket	1	pcs.	18.66	#6	18.66 ✓	20.15
5E6919485	Sensor Bracket	1	pcs.	18.66	#6	18.66 ✓	20.15
5E6919486	Sensor Bracket	1	pcs.	18.66	#6	18.66 ✓	20.15
5E7919486A	Sensor Bracket	1	pcs.	18.66	#6	18.66 ✓	20.15
5E6807521 9B9	Unbekannt	1	pcs.	273.69	#6	273.69 ✓	295.59
	RR BUMPER LOWER SPOILER <i>? Xan</i>	1	pcs.	273.69	#6	273.69 ✓	295.59
	LABOUR						
	Spray Painting	3	pcs.	840.00	#6	2,520.00 <i>840</i>	2,721.60
	CHINA TAIPING DIRECT				#6	2,400.00 <i>800</i>	2,592.00
	DOA:03/02/2023						
	TP VEH NO: SJY2240K						
	SURVEY BY:						

Quotation valid till 13-02-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	9,040.81	8%	784.06	9,800.81	10,584.87
Total	760.00	9,040.81		784.06	9,800.81	10,584.87

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
ZHANG
XIAOTONG
BLK 138A YUAN CHING ROAD
#17-115
SINGAPORE 611138

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

06-02-2023
5211001170
200208384E
30001
2023003349/ 1
06-02-2023
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMJ9634E	NX34JDS1	07-01-2022	TMBBR7NX4MY179745	OCTAVIA M-HEVSTY TS110/1.5A7F	20

Customer


Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
3 days
08/02/23 e15w
Reply before print