

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Romeo Jonnalyn Alaan

Date: 09 Feb 2023

**Preliminary Advice**

Vehicle No	: SLF8414M	Accident Date	: 04/02/2023
Make	: TOYOTA WISH	Policy No.	: MP306018
Assignment Date	: 07/02/2023	Excess	: S\$600.00
Date of Inspection	: 08/02/2023	Est. Duration of Repair	: 4
Inspection At	: SME MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,677.10
Revised Amount	:S\$	2,619.10
Check Items (Estimated)	:S\$	6,328.00
Total	:S\$	8,947.10

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	33,640.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,360.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part Repair.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs