

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Romeo Jonnalyn Alaan

Date: 02 Mar 2023

Preliminary Advice

Vehicle No	: SLF8414M	Accident Date	: 04/02/2023
Make	: TOYOTA WISH	Policy No.	: MP306018
Assignment Date	: 07/02/2023	Excess	: S\$600.00
Date of Inspection	: 08/02/2023	Est. Duration of Repair	: 4 days
Inspection At	: SME MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,007.60	(Est \$9,677.10 + 1st Supp \$1,171.00 + 2nd Supp \$159.50)
Revised Amount	:S\$	10,838.60	(inclu. \$159.50)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	10,838.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	33,640.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,360.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on the supplementary Items.