



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/HSB23001285/Tpa3q2 Date: 20/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7272T	Veh. Inspected	SNE 5759U
	Policy No.	P2478218	Coverage (\$)	0.00
	Claim No.	S3M04J23	Excess (\$)	0.00
	Assign From		Assign Date	07/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	ZWR800522379	Colour	BLACK
	Odometer	100357 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FIRENZA	6 mm
	L/H Front Tyre	195/65 R15	FIRENZA	6 mm
	R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
	L/H Rear Tyre	195/65 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/01/2023	Inspection Date	08/02/2023
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	