



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 SINGAPORE 737869

HP: 98888885/97816380

## Estimation

Date: 8/2/2023

Vehicle: SNE5759U

Make / Model: TOYOTA NOAH

Chassis No:

| No. | Description                | Unit | Unit Price               | Amount      |
|-----|----------------------------|------|--------------------------|-------------|
| 1   | SLIDING DOOR LH            | 1    | \$ 2,259.45              | \$ 2,259.45 |
| 2   | REAR FENDER LH             | 1    | \$ 1,598.00              | \$ 1,598.00 |
| 3   | REAR BUMPER                | 1    | \$ 798.00                | \$ 798.00   |
|     | TOTAL PART                 |      |                          | \$ 4,655.45 |
|     | LIST DOWN                  | 25%  |                          | \$ 1,163.86 |
|     | AFTER LIST DOWN            |      |                          | \$ 3,491.59 |
|     | SPECIAL NETT               |      |                          |             |
| 1   | REAR DOOR STICKER          | 1    | \$ 200.00                | \$ 200.00   |
| 2   | REAR SPORTS RIM LH         | 1    | \$ 600.00                | \$ 600.00   |
|     |                            |      |                          | \$ 800.00   |
|     | LABOUR                     |      |                          |             |
| 1   | TO CHECK ELECTRICAL WIRING | 1    | \$ 50.00                 | \$ 50.00    |
| 2   | ANTI RUST COAT             | 1    | \$ 150.00                | \$ 150.00   |
| 3   | PANEL BEAT EFFECTED AREAS  | 1    | \$ 600.00                | \$ 600.00   |
| 4   | SPRAY PAINT ACCIDENT AREAS | 1    | \$ 800.00                | \$ 800.00   |
|     | TOTAL AMOUNT               |      |                          | \$ 1,600.00 |
|     |                            |      | Parts Replacement Amount | \$ 3,491.59 |
|     |                            |      | Total Amount for Labour  | \$ 2,400.00 |
|     |                            |      | Total Amount             | \$ 5,891.59 |

Taufik 97495449  
WP- 8/2/23 @ 1240  
Taufik @ 11hantow  
- 3 days  
Repair after repair

1000  
250  
1250  
- 3 days  
\*