

TP SCDF.
KMH LN41ETNU157 580 Xiao Chen.

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
		Date	22-Feb-2023	
		Vehicle No.	SMZ1639K	
		Model	Hyundai Avante	
		CHASSIS/ENG#		
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	Rear Bootlid <i>Dented.</i>	1	\$2,032.20	\$2,032.20 ✓
2	Bootlid Upper Garnish <i>Not new</i>	1	\$398.70	\$398.70 X.
3	Bootlid Lock <i>Damaged.</i>	1	\$176.20	\$176.20 ✓
4	Bootlid Lock Switch <i>Not new</i>	1	\$101.40	\$101.40 X.
5	Bootlid Reflector Assembly <i>cracked.</i>	1	\$1,273.00	\$1,273.00 ✓
6	Bootlid Logo <i>New</i>	1	\$28.10	\$28.10 ✓
7	Bootlid Emblem - Avante <i>New</i>	1	\$36.10	\$36.10 ✓
8	Bootlid Catch <i>Not new</i>	1	\$23.10	\$23.10 X.
9	Bootlid Weatherstrip <i>new</i>	1	\$108.30	\$108.30 X
10	Bootlid Inner Trimboard <i>new</i>	1	\$120.80	\$120.80 X.
11	Tail Lamp LH&RH <i>cracked.</i>	2	\$876.80	\$1,753.60 ✓
12	Rear Bumper <i>Deformed.</i>	1	\$598.00	\$598.00 ✓
13	Rear Bumper Retainer <i>Not new</i>	2	\$49.00	\$98.00 X.
14	Rear Bumper Reflector <i>LH cracked.</i>	2	\$50.20	\$100.40 50.20.
15	Rear Bumper Fog Lamp Assembly <i>Not new</i>	1	\$361.50	\$361.50 X.
16	Rear Bumper Lower Skirt <i>Deformed.</i>	1	\$340.60	\$340.60 ✓
17	Rear Bumper Reinforcement <i>Distorted.</i>	1	\$395.00	\$395.00 ✓
18	Rear Bumper Reinforcement Bracket <i>3 damaged</i>	5	\$22.00	\$110.00 66.
19	Rear Bumper Undercover LH&RH <i>Not new</i>	2	\$67.60	\$135.20 X.
20	Rear End Panel <i>Dented.</i>	1	\$484.80	\$484.80 ✓
21	Rear End Panel Top Garnish <i>Deformed.</i>	1	\$215.80	\$215.80 ✓
Sub-total 1				\$8,890.80
NETT ITEMS				
S/N	Item	Quantity	Unit Price	Amount
1	Reverse Sensor Set <i>Damaged.</i>	1	\$250.00	\$250.00 200
2	Tail Lamp Clip <i>New</i>	4	\$15.00	\$60.00 20.
3	Bootlid Inner Trim Board Clip Set <i>new</i>	1	\$50.00	\$50.00 X.
4	Rear Bumper Clip Set <i>new</i>	1	\$50.00	\$50.00 30.
5	Rear Bumper Lower Skirt Clip Set <i>new</i>	1	\$50.00	\$50.00 20.
6	Rear End Panel Garnish Clip Set <i>new</i>	1	\$50.00	\$50.00 10
7	Rear End Panel Sealant <i>new</i>	1	\$60.00	\$60.00 ✓
Sub-total 2				\$570.00
LABOUR				
1	To change damage parts, repair, align body structure on affected pa			\$1,200.00 800
2	Spray painting on all affected parts (Rear portion)			\$1,400.00 800
3	To remove and transfer tailgate inner mechanism			\$120.00 60
4	To remove and replace reverse sensors			\$40.00 ✓
5	To apply rust coating			\$200.00 60.
6	To conduct wiring checks			\$80.00 30
7	To remove and refit upholstery to facilitate repair			\$200.00 60.

7449.60
5959.68

340

8	To diagnose fault code and reset memory		\$300.00 - 120.
		Labour Total	\$3,540.00
		Parts & Labour Total	\$13,000.80

1970

total: 8269.68

L/s: 6.6K ✓

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: