

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001290/KPA3Q2**Date:** 12/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_02

Claimant Vehicle No : SJA8991M**Insured Vehicle No :** SHD2238C

Date of Loss: 31/01/2023

Nature of Claim: TP

Claim No: MFL2023D0005058

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJA8991M**

Make & Model: BMW 520I, 2.0 M SPORT HYBRID (A)

Engine No: B48B20A25706352

Reg. Date: 17/06/2021 (Man. Year: 2021)

Chassis No: WBA72AG020WX17269

Colour: Metallic Pearl White

Odometer: 13642 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 275/75 R19

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		6,684.66		
(S\$)	0.00	6,684.66	-6,684.66	
+ GST 8.00/8.00% (S\$)	0.00	534.77	-534.77	
Nett Amount (S\$)	0.00	7,219.43	-7,219.43	
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		7,546.18		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment: 07/02/2023

Date Inspected: 08/02/2023 Inspected At:

Motor Edgevantage Pte Ltd (HQ)

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
Parts:	143	BMW 520I 2.0 M SPORT HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA8991M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >