

ASS. REC. BY:

REF:

INC/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / ~~Com~~ / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: ~~Good~~ / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ~~Nil~~ / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8430h, Kenneth finalised (Red \$2920.98, 87%)
(No Lump Sum)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trlp:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S - RS. SI

) Parts

) Others

Report Format :

TP

Lump Sum / I.B.I. (\$

430

TOTAL

**FORZA AUTOHAUS PTE LTD**

39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS
SINGAPORE 737856
TEL: 62781889 EMAIL: ENQUIRY@FORZAAUTO.SG
CO./GST REG: 201833292C

ESTIMATE

CYK ENGINEERING PTE LTD
5 SOON LEE STREET #05-46 PIONEER POINT
Singapore 627607
Contact No. : 91526821

Code : E23020004
Date In : 03/02/2023
Vehicle No. : GBF2107H
Model : TOYOTA, DYNA 3.0 M
Chassis No. : KDY2318024305

Parts and Labour Assessment

Description	Qty	Unit Price	Amount
Parts & Services			
FRONT FENDER LH	1.00	378.20	<i>n</i> 378.20 <i>X</i>
FRONT DOOR LH	1.00	1,423.10	<i>n</i> 1,423.10 <i>X</i>
Subtotal Before Discount S\$			1,801.30
25.00% Discount S\$			450.32
Subtotal S\$			1,350.98
Parts & Services Total S\$			1,350.98

Labour

TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,000.00	1,000.00 <i>2da</i>
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,000.00	1,000.00 <i>15da</i>
Subtotal S\$			2,000.00
Labour Total S\$			2,000.00

*Not Withclaim
Repair After Paint
2day
\$430/-*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts & Services Total S\$

1,350.98