

(08/11/13) wef

ASS. REC. BY: Rum

REF:

CS/LPC 23001299/Rwy3

433A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SLN 8964Mat Workshop m/s Wah Homof 48, 10th Guan

Insured:

LPC

Policy No.

Claims No.

Sum Insured:

Excess:

NIL

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

81K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 8964M

Yr Regn:

2017 / 06CType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA WISH 1.8 CVTc.c 1798

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDX 20W 003 008 233

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

02/02/03

D.O.I.

07/02/23

Survey held at

Wah HomDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 39K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLU8964M TOYOTA WISH 1.8 CVT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front windscreen <i>cm</i>		600.00	
1	Front windscreen moulding <i>an</i>		60.00	
1	Dashboard <i>form</i>		700.00	
1	Passenger airbag <i>act</i>		1200.00	
1	Steering wheel airbag <i>act</i>		900.00	
1	Steering angle sensor <i>act</i>		280.00	
1	Driver safety belt <i>act</i>		380.00	
1	Passenger safety belt <i>act</i>		380.00	
1	Airbag ecu <i>act</i>		450.00	
1	Airbag front sensor LH/RH @2*\$150 <i>act</i>		300.00	
1	Wheel housing rh <i>bt</i>		270.00	
2	Front fender Lh/rh @2*\$320 <i>buc</i>		640.00	
2	Front fender shield Lh/rh @2*\$90 <i>form</i>		180.00	
1	Bonnet <i>buc</i>		300.00	
1	Bonnet insulator <i>de</i>		180.00	
2	Bonnet hinge Lh/rh @2*\$45 <i>bt</i>		90.00	
1	Bonnet lock <i>bt</i>		70.00	
1	Bonnet lock badge <i>new</i>		30.00	
2	Bonnet stopper <i>an</i>		10.00	
1	Bonnet stand <i>X</i>		35.00	
1	Bonnet stand holder <i>X</i>		25.00	
1	Wiper top garnish <i>cut</i>		200.00	
1	Support panel <i>bt</i>		580.00	
2	Radiator air guide upper Lh/rh @2*\$45 ?		90.00	
2	Radiator air guide lower Lh/rh @2*\$45 ?		90.00	
1	Brace panel no. 53208a <i>bt</i>		75.00	
1	Radiator top garnish <i>de</i>		70.00	
1	Fr bumper <i>form</i>		240.00	
2	Fr bumper side retainer Lh/rh @2*\$40 <i>an</i>		80.00	
1	Front bumper lower cover <i>cm</i>		120.00	
1	Fr bumper sponge <i>cm</i>		60.00	
1	Front reinforcement <i>bt</i>		140.00	
4	Front reinforcement screw 4pcs <i>an</i>			
2	Fog lamp Lh/rh @2*\$90 <i>cm</i>		180.00	
2	Fog lamp cover Lh/rh @2*\$50 <i>cut</i>		100.00	
2	Fog lamp side bracket Lh/rh @2*\$45 <i>dis</i>		90.00	
2	Fog lamp side cover Lh/rh <i>cm</i>			
1	Center grille assy <i>cm</i>			
1	Condense <i>bt</i>		450.00	
1	Radiator <i>bt</i>		580.00	
1	Fan cowling ?		120.00	
1	Fan cowling top garnish ?		45.00	
2	Fan cowling top bracket Lh/rh @2*\$20 ?		40.00	
1	Fan blade Lh/rh @2*\$80 ?		160.00	
1	Fan motor lh/rh @2*\$180 ?		360.00	
1	Radiator top hose ?		25.00	

1	Radiator lower hose	25.00	
1	Coolant spare tank	90.00	
1	Intake manifold	380.00	
1	Engine top cover	180.00	
2	Headlamp Lh/rh @2*\$380	760.00	
2	Headlamp control unit Lh/rh @2*\$320	640.00	
1	Engine lower cover	90.00	
1	Aircon pipe (condenser to compressor)	220.00	
1	Aircon pipe (condenser to valve)	240.00	
1	Air cleaner box assy	320.00	
1	Air cleaner box lower pipe bottom	90.00	
1	Air cleaner box lower pipe top	75.00	
1	Battery lower tray	30.00	
1	Battery top bracket	40.00	
1	Battery side rod	40.00	
1	Engine mounting top Lh	90.00	
1	Engine mounting top rh	130.00	
1	Engine mounting lower front	80.00	
1	Engine mount lower back	90.00	
1	Wiper tank	75.00	
1	Wiper tank motor	75.00	
1	Engine wire harness	2200.00	
1	Fuse box upper cover	50.00	
1	Fuse box lower cover	75.00	
1	Fuse box center assy	70.00	
1	Gearbox	7800.00	
2	Chassis member LH/RH (Repair refer to labour)	0.00	
2	Front door RH/LH (Repair refer to labour)	0.00	
		24930.00	
		3739.50	
		28669.50	
		Plus 15%	
		29629.50	
SPECIAL NETT ITEMS			
1	Front bumper clips	35.00	30
1	Bonnet insulator clips	35.00	30
1	Front carplate with cover	35.00	/
1	Front windscreen sealant	50.00	/
1	Center grille clips	30.00	/
2	Front fender shield LH/RH clips	50.00	30
1	Battery	280.00	150
2	Headlamp light bulb LH/RH @2*\$30	60.00	X
2	Headlamp dim light bulb LH/RH @2*\$20	40.00	X
2	Headlamp signal light bulb LH/RH @2*\$20	40.00	X
2	Fog lamp light bulb LH/RH @2*\$30	60.00	X
1	Engine lower cover clips	35.00	30
1	Gearbox fluid	100.00	60
1	Coolant	50.00	/
1	Wheel hosung LH sealant	50.00	30
1	ERP sticker	10.00	/
Total Parts		29629.50	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Vehicle No. SLU8964M TOYOTA WISH 1.8 CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2000.00	1200 1500
2	To supply paint materials, expandable items & partly respray paint on parts replaced & repaired	1800.00	1600
3	To remove and refix/replace/repair wiring system at accident damaged area and check for all electrical proper function	400.00	200
4	To refix both side safety belt fitting and upholster garnish	100.00	60
5	To remove and refit front windscreen	100.00	
6	Remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	100.00	
7	Online coding resets	250.00	200
8	Remove and replace dashboard and related wire harness and related parts	250.00	150
9	To carried out remove and replace engine mounting set <i>phls</i>	200.00	100?
10	To carried out remove and replace gearbox <i>phls</i>	500.00	250?
Labour Total :		5700.00	
TOTAL (PARTS & LABOUR):		35329.50	

Panel
Hp 900/100/68
14 days
L/S
07/02/23 @ 1600
EXCESS: TBA
REVIEW
Revy after repair

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	433H
Vehicle Details	
Vehicle No.:	SLU8964M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR0A29780
Chassis No.:	JTDGG20W00J008233
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	18 Dec 2017
First Registration Date:	18 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2027
PARF Rebate Amount:	\$13,968.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$27,904.00
Total Rebate Amount:	\$41,872.00

The information contained herein is correct as at 07 Feb 2023

Toyota Wish 1.8A

Overview

Financial

Accessories

Similar

Research

Photos

Map



**Certified
Pre-☒Owned**

The **BEST** for you

Price	\$75,800		
Depreciation	\$14,880 /yr View models with similar depre	Reg Date	12-Jul-2017 (4yrs 5mths 4days COE left)
Mileage	114,200 km (20.5k /yr)	Manufactured	2017
Road Tax	\$976 /yr	Transmission	Auto
Dereg Value	\$34,996 as of today (change)	OMV	\$19,955
COE	\$48,001	ARF	\$19,955
Engine Cap	1,798 cc	Power	105.0 kW (140 bhp)
Curb Weight	1,355 kg	No. of Owners	1