

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 29 Mar 2023

Preliminary Advice

Insured Vehicle No	: SLX9560Y	Accident Date	: 28/01/2023
TP Vehicle No	: SLS3511E	Assignment Date	: 07/02/2023
Make	: MERCEDES-BENZ E200	Est. Duration of Repair	: 4
Date of Inspection	: 21/03/2023		
Inspection At	: Z-ONE AUTOMOTIVE PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6, BLK D #01-87, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,673.00
Revised Amount	:S\$	5,314.01
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,314.01

Lump Sum Repair	:S\$	4,250.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	215,000.00
COE / PARF Rebate	:S\$	86,945.00
Salvage Value	:S\$	
Margin for Repair	:S\$	128,055.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.