



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE

GST Registration No. 201118055N Company Registration No: 201118055N

ESTIMATE

JACK NG CHIN POH
BLK 303 WOODLANDS ST 31 #03-163 Singapore
730303

Contact : 96753119 96753119

Code : C102059

Date in : 20/03/2023

Vehicle Num. : SLS3511E

Model : MERCEDES BENZ E200 M-HYBRID EXC
LUSIVE SALOON AUTO

Chassis/Eng# : W1K2130802A905875/26492030347642

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Kick sensor	2	190.00 <i>em</i>	380.00 <i>1P2</i>
Rear Boot 'E200' Emblem	<i>102.00</i> 1	165.00 <i>mer</i>	165.00 <i>/</i>
Rear Boot 'Logo' Emblem	1	75.00 <i>17</i>	75.00 <i>X</i>
Rear Boot Lid	1	2950.00 <i>12</i>	2,950.00 <i>X</i>
Rear Boot Lid Chrome	1	130.00 <i>17</i>	130.00 <i>X</i>
Rear Boot Lid Weather Strip	1	265.00 <i>17</i>	265.00 <i>X</i>
Rear Boot Taillight L/R	2	602.00 <i>17</i>	1,204.00 <i>X</i>
Rear Bumper	<i>2171.46</i> 1	2320.00 <i>20/22</i>	2,320.00 <i>/</i>
Rear Bumper Centre Bracket	1	125.00 <i>cu</i>	125.00 <i>/</i>
Rear Bumper Chrome Centre	<i>389.53</i> 1	430.00 <i>cu</i>	430.00 <i>/</i>
Rear Bumper Chrome Side L/R	2	65.00 <i>su</i>	130.00 <i>X</i>
Rear Bumper Reflector L/R	2	62.00 <i>17</i>	124.00 <i>X</i>
Rear Bumper Retainer L/R	2	204.00 <i>17</i>	408.00 <i>X</i>
Rear End Panel	1	2115.00 <i>R</i>	2,115.00 <i>X</i>
Rear Reinforcement Beam	<i>1039.80</i> 1	1115.00 <i>304</i>	1,115.00 <i>/</i>
Rear Tail Lamp L/R	2	847.00 <i>17</i>	1,694.00 <i>X</i>
Reverse Sensor	4	210.00 <i>shhd</i>	840.00 <i>2pgs</i>

page 1

not attached
see
21/3/23
Warranty open up
4 days
4250



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

Subtotal before discount		14,470.00
Percentage discount	10%	1,447.00
Sub-total 1		13,023.00
Rear Bumper Clips Set (SN)	1	50.00 <i>rec</i> 50.00 ✓
Rear Number Plate Set (SN)	1	50.00 <i>u7</i> 50.00 X
Subtotal before discount		100.00
Percentage discount	0%	0.00
Sub-total 2		100.00
Parts-total		13,123.00

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	120.00 <i>20</i>
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	<i>u7</i> 150.00 X
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	150.00 <i>50</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00 <i>600</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,300.00 <i>600</i>
To recalibrate reverse sensor assy	<i>reput</i> 450.00 X
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	<i>u7</i> 180.00 X
Labour Total	3,550.00
Parts & Labour Total	16,673.00

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-4437-79
127
3994.01
50
1270
5314.01
4251