

Name & Address:
ERGO INSURANCE PTE. LTD.
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985

Email/Fax No:

Contact No:

Vehicle No:
 SMJ6019B
 Brand & Model:
 MX-5

Chassis/VIN No:
 JM6ND2E7A0200015

Contact Person (Eurokars)/Wip No:
 LIM / 55338

Type of Claim:

Policy No:

Contact No (Eurokars):

THIRD PARTY

12/03/2018

PARTS / MATERIAL CHARGES

MARK = Survey Marking (Key "A" if item is approved)					
NO	DESCRIPTION	PART NO.	QTY	MARK	PRICE
1	FRONT BUMPER <i>de, ? ca</i>	MN2Y1-50-03X 88	1	-	\$ 1,411.96
2	MESH FRONT BUMPER	MN243-50-1T08	1	-	\$ 309.75
3	BRACKET TOP FRONT GRILLE <i>X n</i>	MN243-50-722D	1	-	\$ 130.73
4	RETAINER RH FRONT <i>X n</i>	MN314-50-0T1A	1	-	\$ 13.91
5	RETAINER LH FRONT <i>X n</i>	MN314-50-0U1A	1	-	\$ 12.98
6	NUT, CLIP <i>n</i>	MC274-50-133	8	-	\$ 18.88
7	FRONT REINFORCEMENT <i>? X n</i>	MN243-50-070D	1	-	\$ 1,143.51
8	AIR GUIDE RH FRONT REINFORCEMENT	MNA1J-50-A21	1	-	\$ 29.42
9	FASTENER <i>n</i>	MFD01-68-AC3	1	-	\$ 5.31
10	RIVET <i>n</i>	MBN8F-50-35S	4	-	\$ 18.56
11	CLIP <i>n</i>	MEA01-50-037	4	-	\$ 29.36
12	LOWER SKIRT RH FRONT <i>X n</i>	MN243-51-9H1	1	-	\$ 203.22
13	LOWER SKIRT LH FRONT <i>X n</i>	MN243-51-9L1	1	-	\$ 203.22
14	RIVET <i>n</i>	MBN8F-50-35S	4	-	\$ 18.56
15	FASTENER <i>X n</i>	MB33I-51-833	8	-	\$ 51.92
16	MASCOT FRONT <i>n</i>	MN243-51-741	1	-	\$ 80.67
17					\$ -

Sub-Total (Parts Price) \$ - \$ 3,681.96

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER.		\$ 660 800.00
2	TO RESPRAY FRONT BUMPER.		\$ 630 700.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 180 250.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 200 300.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CADUTCHOUQ).		\$ X 250.00
6	SUNDRIES.		\$ 20 20.00

Survey Date & Time:

Repair Days:

Excess:

Sub-Total (Labour Price) \$ - \$ 2,350.00

Surveyor Remarks:

	REVISED	PRICE
Parts Price	\$ -	\$ 3,681.96
Labour Price	\$ -	\$ 2,350.00
Total (Initial Estimate)	\$ -	\$ 6,031.96
Supp 1	\$ -	\$ -

REPAIR ESTIMATE

Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	6,031.96
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	6,031.96
GST	8%	\$	-	\$ 482.56
GRAND TOTAL	\$	-	\$	6,514.52

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
HP 900ws 68
3 days
P/P
23/02/23 @ 1400
Rony before part