

Name & Address:

ERGO INSURANCE PTE. LTD.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Vehicle No:

SMJ6019B

Brand & Model:

MX-5

Date:

14-Apr-23

Email/Fax No:

Contact No:

Chassis/VIN No:

JM6ND2E7AJ0200015

Contact Person (Eurokars)/Wip No:

LIM / 55338

Type of Claim:

THIRD PARTY

Policy No:

Date Of Registration:

12/03/2018

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	MN2Y1-50-03X BB	1	A	\$ 1,411.96	\$ 1,411.96
2	MESH FRONT BUMPER	MN243-50-1T0B	1	A	\$ 309.75	\$ 309.75
3	BRACKET TOP FRONT GRILLE	MN243-50-722D	1		\$ -	\$ 130.73
4	RETAINER RH FRONT	MN314-50-0T1A	1		\$ -	\$ 13.91
5	RETAINER LH FRONT	MN314-50-0U1A	1		\$ -	\$ 12.98
6	NUT,CLIP	MC274-50-133	8	A	\$ 18.88	\$ 18.88
7	FRONT REINFORCEMENT	MN243-50-070D	1		\$ -	\$ 1,143.51
8	AIR GUIDE RH FRONT REINFORCEMENT	MNA1J-50-A21	1		\$ -	\$ 29.42
9	FASTENER	MFD01-68-AC3	1	A	\$ 5.31	\$ 5.31
10	RIVET	MBN8F-50-355	4	A	\$ 18.56	\$ 18.56
11	CLIP	MEA01-50-037	4	A	\$ 29.36	\$ 29.36
12	LOWER SKIRT RH FRONT	MN243-51-9H1	1		\$ -	\$ 203.22
13	LOWER SKIRT LH FRONT	MN243-51-9L1	1		\$ -	\$ 203.22
14	RIVET	MBN8F-50-355	2	A	\$ 9.28	\$ 18.56
15	FASTENER	MB33J-51-833	8	A	\$ 51.92	\$ 51.92
16	MASCOT FRONT	MN243-51-741	1	A	\$ 80.67	\$ 80.67
17						\$ -

Sub-Total (Parts Price) \$ 1,935.69 \$ 3,681.96

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER.	\$ 660.00	\$ 800.00
2	TO RESPRAY FRONT BUMPER.	\$ 630.00	\$ 700.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 180.00	\$ 250.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 200.00	\$ 300.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC).	\$ -	\$ 250.00
6	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:

Repair Days: 3

Excess:

Sub-Total (Labour Price) \$ 1,690.00 \$ 2,350.00

Surveyor Remarks:

	REVISED	PRICE
Parts Price	\$ 1,935.69	\$ 3,681.96
Labour Price	\$ 1,690.00	\$ 2,350.00
Total (Initial Estimate)	\$ 3,625.69	\$ 6,031.96

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

FINALIZATION

Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	3,625.69	\$	6,031.96
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	3,625.69	\$	6,031.96
GST	8%	\$	290.06	\$ 482.56
GRAND TOTAL		\$	3,915.75	\$ 6,514.52