

JDM AUTOCARE

BLK 1 KAKI BUKIT AVENUE 6, #01-51, AutoBay@Kaki Bukit Singapore 417883
REGISTRATION NO. / UNIQUE ENTITY NUMBER : 53060650W

DATE : 06/02/2023

VEHICLE NO : SLU4055M MAZDA 3 HB

ITEMS	QTY	Amount
1 LH FRONT LOWER ARM <i>Best</i>	1	\$541.30 ✓
2 LH FRONT KNUCKLER ARM <i>Best</i>	1	\$681.40 ✓
3 LH FRONT KNUCKLER ARM BEARING <i>Best</i>	1	\$198.40 ✓
4 LH FRONT SHOCK ABSORBER <i>New</i>	1	\$542.80 ✕
5 FRONT STEERING RACK & PINION <i>New</i>	1	\$1,493.70 +
6 LH FRONT DRIVE SHAFT	1	\$112.60 ✕
7 LH FRONT BUMPER SIDE RETAINER <i>New</i>	1	\$65.70 +
8 LH FRONT FENDER <i>Dented</i>	1	\$348.71 ✓
9 LH FRONT FENDER INNER COWLING <i>Dented</i>	1	\$134.80 ✓
10 LH FRONT DOOR <i>Dented</i>	1	\$1,228.97 ✓
11 LH FRONT DOOR HINGE <i>Best</i>	2	\$165.90 ✓
12 LH FRONT DOOR CHEKCR <i>New</i>	1	\$126.10 ✕
13 LH FRONT DOOR INNER TRIM <i>Cracked</i>	1	\$658.10 ✓
14 LH FRONT FRONT DOOR WEATHE STRIPE <i>Get</i>	1	\$260.40 ✓
15 LH FRONT DOOR STCIKER <i>New</i>	1	\$156.10 ✓
16 LH FRONT DOOR OUTER MOULDING <i>New</i>	1	\$212.30 +
17 LH FRONT DOOR OUTER HANDLER	1	\$259.70 +
18 LH FRONT DOOR POWER WINDOW MOTOR <i>New</i>	1	\$564.20 +
19 LH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>Dented</i>	1	\$664.20 ✓
20 LH FRONT DOOR GLASS <i>New</i>	1	\$567.30 +
21 LH FRONT DOOR GLASS CHANNEL RUBBER <i>New</i>	1	\$126.80 ✕
22 LH FRONT DOOR MIRROR <i>Best</i>	1	\$698.30 ✓
23 LH FRONT DOOR MIRROR COVER <i>Best</i>	1	\$112.80 ✕
24 LH ROCKER PANEL OUTER PANEL <i>Best</i>	1	\$1,154.20 ✕
25 LH REAR DOOR <i>Dented</i>	1	\$1,175.41 ✓
26 LH REAR DOOR HINGE	2	\$165.90 +
27 LH REAR DOOR CHEKCR <i>New</i>	1	\$126.10 ✕
28 LH REAR DOOR INNER TRIM	1	\$658.10 +
29 LH REAR DOOR WEATHE STRIPE	1	\$260.40 ✓
30 LH REAR DOOR STICKER <i>New</i>	1	\$156.10 ✓
31 LH REAR DOOR OUTER MOULDING <i>New</i>	1	\$212.30 +
32 LH REAR DOOR OUTER HANDLER	1	\$259.70 +
33 LH REAR DOOR POWER WINDOW MOTOR	1	\$564.20 +
34 LH REAR DOOR POWER WINDOW REGULATOR GEAR <i>New</i>	1	\$664.20 ✕

SLU4055M MAZDA 3 HB

35	LH REAR DOOR GLASS	1	\$567.30	+
36	LH REAR DOOR GLASS CHANNEL RUBBER	1	\$126.80	+

688809

5510.47

DISCOUNT 20%
TOTAL

\$16,011.29

\$3,202.26

\$12,809.03

SPECIAL NETT ITEM

	QTY	Amount
1 FRONT BUMPER CLIPS	1	\$80.00
2 LH FRONT FENDER INNER COWLING CLIPS	1	\$60.00
3 LH FRONT DOOR INNER TRIM BOARD CLIPS	1	\$80.00
4 LH REAR DOOR INNER TRIM BOARD CLIPS	1	\$80.00
5 LH FRONT SPORT RIM	1	\$950.00
6 LH FRONT TYRE	1	\$380.00

\$1,630.00

\$14,439.03

Labour charges

- TO REMOVE , REINSTALL ALL ELECTRICAL WIRING , LIGHTING
- TO SUPPLY LABOUR , WORKMANSHIP TO REMOVE AND REINSTALL AFFECTED AREAS
- TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS
- TO APPLY TUFF COAT
- TO TRANSFER LH BOTH DOOR GLASS
- TO TRANSFER LH BOTH DOOR FITTING
- TO REMOVE & RENEW LH FRONT UNDERCASRRRIAGE
- WHEEL ALIGNMENT

800

\$80.00 30.
\$1,500.00 800.
\$1,200.00 900.
\$300.00 80.
\$260.00 80.
\$300.00 80.
\$300.00 200.
\$150.00 80

\$4,090.00

\$18,529.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan G
w/s 06/02/23.

07.05 Days

total: 8410.47
2/5: 6.7K.