

Vehicle Damage Assessment Report for [SLU4055M]

Estimate Created: 21/03/2023 13:33 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 21/03/2023 14:06 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mazda	Model	3
Engine Type			
License Plate Number	SLU4055M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$6,700.00 WITH 7 WORKING
DAYS

Insurlogic 4 (21/03/2023 14:06)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
LH front lower arm		1	541.30	-20.00 %	433.04
LH front knuckle arm		1	681.40	-20.00 %	545.12
LH front knuckle arm bearing		1	198.40	-20.00 %	158.72
LH front fender		1	348.71	-20.00 %	278.97
LH front fender inner cowling		1	134.80	-20.00 %	107.84
LH front door		1	1228.97	-20.00 %	983.18
LH front door hinge		2	82.95	-20.00 %	132.72
LH front door inner trim		1	658.10	-20.00 %	526.48
LH front door weatherstrip		1	260.40	-20.00 %	208.32
LH front door sticker		1	156.10	-20.00 %	124.88
LH front door power window regulator gear		1	664.20	-20.00 %	531.36
LH front door mirror		1	698.30	-20.00 %	558.64
LH rear door		1	1175.41	-20.00 %	940.33
LH rear door sticker		1	156.10	-20.00 %	124.88

Parts Subtotal 5,654.48

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
LH front fender inner cowling clips		1.0	30.00	0.00 %	30.00
LH rear door inner trim board clips		1.0	30.00	0.00 %	30.00
LH front sport rim		1.0	580.00	0.00 %	580.00
LH front door inner trim board clips		1.0	30.00	0.00 %	30.00

Materials Subtotal 670.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove, reinstall all electrical wiring, lighting.	RnR	30.00	0.00 %	30.00
To supply labour, workmanship to remove and reinstall affected areas.	RnR	700.00	0.00 %	700.00
To apply tuff coat	RnR	60.00	0.00 %	60.00
To transfer LH both door fitting	RnR	80.00	0.00 %	80.00

To remove and renew LH front undercarriage	RnR	200.00	0.00 %	200.00
wheel alignment	RnR	80.00	0.00 %	80.00
To transfer LH both door glass	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray painting and respray accident affected areas.	Full spray	800.00	0.00 %	800.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	1,230.00
			Paint Labor Subtotal	800.00
			Labor Subtotal	2,030.00

Summary

Repair Cost	8,354.48
Discount(20 %)	(1,653.69)
	6,700.79
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,700.79