

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 07/02/2023

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB89E
Case Reference Number	BUS/01/23/5020
Registration Date	7/17/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Yik Wei Cheng
Type of Accident	Side Swipe
Accident Date and Time	1/24/2023 7:37 PM
Accident Reported Date and Time	2/3/2023 5:21 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB89E - Right center portion SMK9201R (TP) - INSURED WITH AIG
Prepared Date and Time	2/7/2023 10:34 AM
Chassis Number	WEB63442021000219
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$942.00	\$0.00
Total Spare Part Cost	\$160.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,692.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	07/02/2023 10:41 AM	
Signature		
Remarks		

Tan Jie 97495749
wsp 7/2/23 @ 3pm.
Resurvey after repair
03 days
tan jie @ wkants wu

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2023
User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,590.00				1060			
Total Labour		\$1,590.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$942.00				772			
Total Spray Painting & Panel Beating		\$942.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010227	BODY RH	5019	PANEL SKIRT-R4, FOR MB OC500 BUS	1.00	\$1,442.10	100.00	\$0.00	Repair	Ry
6010229	BODY RH	5021	PANEL SKIRT-R6, FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Repair	Ry
6010230	BODY RH	5022	PANEL SKIRT-R7, FOR MB OC500 BUS	1.00	\$880.50	100.00	\$0.00	Repair	Ry
6010231	BODY RH	5023	PANEL SKIRT-R8, FOR MB OC500 BUS	1.00	\$338.10	100.00	\$0.00	Repair	Ry
			SGLOVEBUS STICKER	1.00	\$200.00	0.00	\$200.00	Replace	net
Total					\$3,378.90		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									