



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CCA PG Service Cash Sales	Cust No/Name /CCA PG Service Cash Sales
CCA Pandan Gardens Cash Sales	Reg No/Reg Date SMP6843G / 10/10/201
209 Pandan Gardens	Date In/Mileage 06/02/2023/ 0
Singapore 609339	Chassis No MMBSTA13AKH002526
Contact No	Engine No 3A92UHX6113
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	07/02/2023/ 10:20	TLK	282 / Kevin Leong	31134
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER, FRT LH FENDER, BODY KIT & AFFECTED AREA		1600		2560.00
E PNT98000	PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR PANEL & BODY KIT		2200		2750.00
E PNT88000	REPLACE REAR BUMPER, BOOT, BOTH REAR FENDER, END PANEL, FLOOR PANEL, BODY KIT & BOTH REAR TAIL LAMP PANEL		6400		8960.00
E PNT98000	REPAIR ON REAR BOTH BOOT SIDE EXTENTION				
E PNT88000	PAINT WORK ON REAR BUMPER, BOOT, BODY KIT, END PANEL, FLOOR PANEL, BOTH REAR TAIL LAMP PANEL & BOTH REAR FENDER		3850		5500.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR		100		150.00
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR				300.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT				80.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR		160		180.00
E PNT88000	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL		180		200.00
E PNT88000	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR		160		180.00
A 13900099	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR		640		620.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA		200		240.00
M SUNDRY	PERFORM RUST PREVENTION		100		180.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM		120		150.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of breakage.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CCA PG Service Cash Sales	Cust No/Name /CCA PG Service Cash Sales
CCA Pandan Gardens Cash Sales	Reg No/Reg Date SMP6843G / 10/10/201
209 Pandan Gardens	Date In/Mileage 06/02/2023/ 0
Singapore 609339	Chassis No MMBSTA13AKH002526
Contact No	Engine No 3A92UHX6113
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	07/02/2023/ 10:20	TLK	282 / Kevin Leong	31134			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								8 60.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								new 50.00
M SUNDRY								30 50.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								
SUNDRIES								
M HEADLAMP ASSY,LH					1.00	1233.00	00.00	new 1233.00
M LAMP ASSY,COMB,RR LH					1.00	661.00	00.00	new 661.00
M LAMP ASSY,COMB,RR RH					1.00	661.00	00.00	new 661.00
M REFLECTOR					1.00	28.00	00.00	28.00
M REFLECTOR					1.00	28.00	00.00	? 28.00
M LAMP ASSY,LICENSE PLATE					2.00	53.00	00.00	? 106.00
M LAMP ASSY,FOG,FR LH					1.00	315.00	00.00	? 315.00
M FACE,FR BUMPER					1.00	995.00	00.00	de 995.00
M GARNISH,FR BUMPER,LH					1.00	157.00	00.00	de 157.00
M GRILLE,FR UNDER					1.00	203.00	00.00	? 203.00
M BRACKET,FR BUMPER,LH					1.00	16.00	00.00	dis 16.00
M FACE,RR BUMPER					1.00	1268.00	00.00	de 1268.00
M BRACKET,RR BUMPER,LH					1.00	34.00	00.00	de 34.00
M BRACKET,RR BUMPER,RH					1.00	34.00	00.00	de 34.00
M FENDER,FR LH					1.00	652.00	00.00	bt 652.00
M FLOOR,RR					1.00	986.00	00.00	? 986.00
M PANEL,RR END					1.00	440.00	00.00	bt 440.00
M SPACER,RR WINDOW					3.00	11.00	00.00	new 33.00
M STOPPER,WINDSHIELD GLASS					2.00	4.00	00.00	new 8.00
M GLASS,RR WINDOW					1.00	561.00	00.00	? 561.00
M HINGE,TRUNK LID,LH					1.00	209.00	00.00	bt 209.00
M HINGE,TRUNK LID,RH					1.00	209.00	00.00	bt 209.00
M WEATHERSTRIP,TRUNK LID					1.00	161.00	00.00	twi 161.00
M PANEL,TRUNK LID					1.00	820.00	00.00	bt 820.00
M LATCH,TRUNK LID					1.00	224.00	00.00	bt 224.00
M GARNISH,RR END PANEL					1.00	346.00	00.00	de 346.00
M MARK,THREE-DIA					1.00	86.00	00.00	new 86.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CCA PG Service Cash Sales	Cust No/Name /CCA PG Service Cash Sales
CCA Pandan Gardens Cash Sales	Reg No/Reg Date SMP6843G / 10/10/201
209 Pandan Gardens	Date In/Mileage 06/02/2023/ 0
Singapore 609339	Chassis No MMBSTA13AKH002526
Contact No	Engine No 3A92UHX6113
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	07/02/2023/ 10:20	TLK	282 / Kevin Leong	31134
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M MARK,ATTRAGE	1.00	26.00	00.00	26.00	26.00
M TRIM,RR END	1.00	68.00	00.00	68.00	68.00
M PANEL,QTR,OTR LH	1.00	1336.00	00.00	1336.00	1336.00
M PANEL,QTR,OTR RH	1.00	1324.00	00.00	1324.00	1324.00
M PANEL,RR COMB LAMP HSG,LH	1.00	62.00	00.00	62.00	62.00
M PANEL,RR COMB LAMP HSG,RH	1.00	62.00	00.00	62.00	62.00
M EXTN,QTR PANEL,UPR OTR LH	1.00	122.00	00.00	122.00	122.00
M EXTN,QTR PANEL,UPR OTR RH	1.00	122.00	00.00	122.00	122.00
M SHIELD,FR WHEELHOUSE,LH	1.00	101.00	00.00	101.00	101.00

Estimate

Tanfah 97495749
wp 2/2/23 240pm
resurvey before paint
tanfah@lehart.com
22-23 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	36,187.00
8% GST on	2894.96
Total Payable	39,081.96

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.