

ASS. REC. BY:

REF:

GRB/23 001312/KCP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WVS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

01/26

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1/ 24 not ready

2/ 10/12 11:00 @ 31000 Cals

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - R.S. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

)

)

)

)

)

)

)

)

Veh No:

SLT 1890T

Yr Regn:

03, 11

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City

c.c.

1497

Colour

m. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

247950

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHGM26509P020380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Westlake

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

5/2/23

D.O.I.

8/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	163D
Vehicle Details	
Vehicle No.:	SLT1890T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5L I-VTEC AUTO
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	L15A71809414
Chassis No.:	MRHGM26509P020380
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,718.00
Original Registration Date:	14 Mar 2011
First Registration Date:	14 Mar 2011
Transfer Count:	2
Actual ARF Paid:	\$18,718.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,069.00
COE Rebate Amount:	\$11,379.00
Total Rebate Amount:	\$11,379.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Feb 2023

OK

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA CITY
Engine/Chassis No.: MRHGM26509P020380
Date of accident: 05.02.23
Damaged area: Rear

Date: 07/02/2023
Claim Type: TP
VRN: SLT1890T

Not Authorized
L1 Sup @ 3100h
Returning After Paint
5 days



List Items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid 503.90 R	1	\$ 1,213.00	\$ 1,213.00	✓
2	Bootlid inner trim L	1	\$ 181.00	\$ 181.00	X
3	Bootlid hinge R	2	\$ 67.00	\$ 134.00	X
4	Bootlid lock 68 R	1	\$ 259.00	\$ 259.00	✓
5	Bootlid release cable L	1	\$ 53.00	\$ 53.00	X
6	Bootlid weatherstrip R/L	1	\$ 185.00	\$ 185.00	50h
7	Bootlid "CITY" emblem R	1	\$ 47.00	\$ 47.00	✓
8	Bootlid "i-VTEC" emblem R	1	\$ 42.00	\$ 42.00	✓
9	Licence plate lamp L	2	\$ 72.00	\$ 144.00	X
10	Bootlid outer chrome garnish L	1	\$ 117.00	\$ 117.00	X
11	Bootlid hinge garnish L	2	\$ 49.00	\$ 98.00	X
12	Bootlid "HONDA" logo R	1	\$ 61.00	\$ 61.00	✓
13	End panel 399.30 R	1	\$ 732.00	\$ 732.00	✓
14	End panel top garnish 98 R	1	\$ 164.00	\$ 164.00	✓
15	Spare tyre floor panel R	1	\$ 895.00	\$ 895.00	X
16	Spare tyre top board L	1	\$ 127.00	\$ 127.00	X
17	Rear bumper 463.70 R	1	\$ 988.00	\$ 988.00	✓
18	Rear bumper side retainer O/S D/R	2	\$ 57.00	\$ 114.00	✓
19	Rear bumper reinforcement N/S	1	\$ 576.00	\$ 576.00	X
20	Rear bumper lower cowl L	1	\$ 188.00	\$ 188.00	X
21	Taillamp C 411.40 C/R / D/R	2	\$ 689.00	\$ 1,378.00	✓
22	Taillamp sponge seal R	2	\$ 8.00	\$ 16.00	✓
23	Taillamp panel R	2	\$ 147.00	\$ 294.00	X
24	Taillamp lower bracket L	2	\$ 33.00	\$ 66.00	X
25	Exhaust assy R	1	\$ 883.00	\$ 883.00	X
26	Exhaust assy mounting L	2	\$ 41.00	\$ 82.00	X
27	Exhaust assy heatshield R	1	\$ 119.00	\$ 119.00	X
Subtotal				\$ 9,156.00	
List discount				20.00%	
Total				\$ 7,324.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: