

ASS. REC. BY: T. Gifford

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$11K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FRM 5244MYr Regn: 2017, Dec.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sniperc.c. 150Colour: Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3 UG 0740M 006720Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 70/90R17R: 60/80R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mm

L/Bal. _____ mm

L/Bal. 9 mm

D.O.A. _____

D.O.I. 08/02/230230Survey held at Project & Mo for work.Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Rep. Format: _____

Lump Sum / I.B. / C. _____

QUOTATION FOR REPAIR :FBM5244M

Qty	Description	Repairer's Estimate
1	SIDE MIRROR SET	120.00 cut / 60
1	CLUTCH LEVER	110.00 bro / 40
1	FRONT MUDGUARD	140.00 cut / 85
1	FRONT HEADLIGHT COVER	140.00 X ny
1	FRONT SIGNAL LHS	110.00 cut / 75
1	FRONT SIGNAL RHS	110.00 X ny
1	FRONT LHS Z PANEL	180.00 wa / 100
1	FRONT BASKET	140.00 wa / 65
1	GEAR SELECTOR LEVER	130.00 bt / 60
1	RIDER FOOTREST BRACKET	140.00 bt / 60
1	SIDE STAND	150.00 bt / 60
1	MAINSTAND	180.00 bt / 95
1	HANDLE GRIP	80.00 cut / 50
1	HANDLE BAR	140.00 bt / 120
1	REAR LHS TAIL COVER	140.00 cut / 120
1	PILLION FOOTREST BRACKET LHS	120.00 X ny
1	PILLION FOOTREST LHS	100.00 cut / 50
1	CHAIN COVER	120.00 X ny
1	REAR TAIL TIDY	180.00 cut / 55
1	REAR SIGNAL LHS	110.00 cut / 60
1	STEERING CONE BEARING	220.00 nel / 50
1	FORK SET	420.00 350 bt -
1	FRONT RIM	450.00 X ny
1	FORK UNDER BRACKET T CONE	220.00 65 bt -
1	FRONT TYRE	200.00 X ny
1	FRONT LHS FOOTPEG	120.00 dd / 50
1	FRONT LHS FOOTPEG RUBBER	100.00 cut / 45
1	HANDLEBAR COVER	140.00 X ny
1	FRONT DRL UNDER COVER	150.00 X ny
1	KEYSWITCH COVER	140.00 X ny
1	TAIL TIDY BRACKET	160.00 X ny

Less 10%	4,960.00
Total Part :	496.00
	4,464.00

Nett items

Total Nett items :	0.00
Total parts :	4,464.00

Labour Fee

FORK ALIGNMENT	220.00 120
FRONT RIM ALIGNMENT	220.00 X
CHASSIS ALIGNMENT	500.00 X
LABOUR FEE	1,200.00 300
	420

Total Labour Fee:	2,140.00
Total parts and labour charges :	6,604.00

7 DAYS

1795
1615.50

Tanpin 97495745
wp 8/2/23

L/S resurvey after repair
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1615.50
420
2035.20
4159/1600
3 days